12/12/19 2016_2025_reserves_expenses.klsx

Willamette Towers HOA Expense Summary by Year 2016 - 2025

2016 Expense Summary

Year	Category	item Name	Expense	Amount
2016	Architectural Interior: Flooring	Hallway Carpets- Labor	15,348	51,416
	Architectural Interior: Flooring	Hallway Carpets- Replace	36,068	51,416
	Architectural Interior: Lighting	Lighting: North Hallway- Renew	1,787	1,787
		Main Entry (South)	7,106	
	Doors	North Stairway Entrance	3,756	18,374
		Stairway (north): Replace on Floors 2 & 3	7,512	
	Garage	Engineer: Assess Structure	3,553	3,553
		Replace Stack Valves- Phase 1 of 2	38,573	38,573
	Plumbing	Restore Drainage on Building's East Side	30,453	30,453
		Engineer: Prescribe Plumbing Updates	5,076	5,076
		2016 Annual Expense Total	149,232	149,232

2016 Expense Summary Revised- Actual Costs

Year	Category	item Name	Expense	Amount
2016	Architectural Interior: Flooring	Hallway Carpets- Labor	39,614	39,614
	— Architectural Interior. Flooring	Hallway Carpets- Replace	33,014	33,014
		1st floor Hallway Flooring	4,127	
	Architectural Interior: Flooring	Primed MDF Baseboard	242	4,869
		Wall Repairs/Re-Painting	500	
	Architectural Interior: Lighting	New Lighting- 6th Floor	1,007	1,007
	Architectural Interior: Paint & Seal-		3,050	3,050
	Lobby Upgrade	Repaint 1st Floor hallway and interior & exterior doors	0.403	
		Main Entry (South)	9,483	40.004
	Doors	North Stairway Entrance	3,429	18,204
		Stairway (north): Replace on Floors 2 & 3	5,292	
	Miscellaneous Repair & Renew:	EntraGuard System Installation	1,895	2,351
	Security- Call Box	EntraGuard System: New Modem	456	,
		Replace Stack Valves: Phase 1 of 2- Piping Job	17,915	
	Plumbing	Pump Replacement- 3 Recirculation Pumps	2,090	17,915
	Doof	East Entry Portico: Replace structural & Re-Roof	4,614	F 2C4
	Roof	East Entry Portico: re-Paint	750	5,364
		2016 Annual Expense Total	94,464	94,464

This item was combined with 2017 Lighting upgrade costs to appear as a single item in 2017 reserves

In future years recirculation pump replacement is paid from Operations

2017 Expense Summary

Year	Category	item Name	Expense	Amount
2017	Architectural Interior: Lighting	All Residence Floors: Replace Lighting	23,576	23,576
	Miscellaneous: Major Items	Paving: Add Asphalt Seal Coat	5,327	31.089
		Ventilation: Clean	25,762	31,089
		2017 Annual Expense Total	54,665	54,665
		2017 Annual Expense Total	54,665	54,

This was not done, re-schedule to ...?

12/12/19 2016_2025_reserves_expenses.xlsx

2017 Expense Summary actual costs

Year	Category	item Name	Expense	Amount
2017	Architectural Interior: Lighting	Replace lighting floors 2-5 & 7-13 (1st & 6th floor are done).	9,760	9,760
	Doors	Electrical work at main entry door	517	517
	Garage: Parking Area Repairs	Remedial work to protect upper deck concrete as-is and to buy time until 2019 complete re-working of the upper deck surface concrete	10,550	10,550
	Miscellaneous: Major Items: Paving: Asphalt Repair	Asphalt surfaces are treated for problems and treated with sealant.	1,970	1,970
	Miscellaneous: Repair and Renew-	Flooring: Entry Carpet	504	504
	Miscellaneous: Repair and Renew - Security: Equipment for Gates	Gate Maintenance	609	609
		Riser valve replacement	36,542	
	DI 1:	Riser Valve Remediation (Asbestos)	3,946	45 500
	Plumbing	Pipe Repair- Replace Manifold line on 1st floor- one time event	5,100	45,588
	_	2017 Annual Expense Total	69,498	69,498

6th floor lighting done in 2016: \$1,007. Combined with this 2017 total, item appears in the Reserves item expenses as \$10,768 for all residential floors (108 fixtures)

2018 Expense Summary update

Year	Category	item Name	Expense	Amount
2018	Doors	ADA (Americans with Disabilities Act) upgrade for lobby doors; East & North Doors.	8,000	8,000
	Plumbing: Remediation	Planned remediation involves replacing some plumbing parts and treating all lines with compressed air.	82,000	82,000
		2018 Annual Expense Total	90,000	90,000

Goal is to clear lines as well as possible of interior metal build-up and buy time regarding plumbing pipe replacement.
Investigation leads the MMRRC (Major Maintenance, Repair and Replacement Committee) to believe that this will help clear plumbing lines and put off major plumbing work for up to 10 years.

2018 Expense Summary actual expenses

Year	Category	item Name	Expense	Amount
2018	Doors	ADA (Americans with Disabilities Act) upgrade for lobby doors; East & North Doors.	7302	7302
	Plumbing: Remediation	Remediation involved replacing some plumbing parts and treating all lines with compressed air.	82000	82000
	Parking Lot Repairs	Items are listed in reserves under Miscellaneous: Major Items- Paving. South Area and North Areas and processes (seal vs. rebuild) are listed separately.	8848	8848
		2018 Annual Actual Expense Total	98150	98150

Cost was as anticipated.

2019 Expense Summary

Year	Category	Item Name	Expense	Amount
2019	Garage	Replace Upper Deck Surface	275000	275000
	Miscellaneous: Repair and Renew: Security: Key / Fob / Entry Guard System	Describe work to be done	8,000	8,000
		2019 Annual Expense Total	283000	283000

Bid may be lower. One estimate is that the cost will now be around \$253,000.

12/12/19 2016_2025_reserves_expenses.xlsx

2019 Expense Summary actual expenses

Year	Category	Item Name	Expense	Amount
2019	Garage	Replace Upper Deck Surface	260,000	260,000
2019	Garage	Re-surface (aluminum oxide) upper deck ramps	7,000	7,000
	Miscellaneous: Repair and Renew:			
	Security: Key / Fob / Entry Guard	Describe work to be done	0	0
	System			
		Install new safety anchors for roof work and for	40.000	40.000
	- Doof	window cleaning	40,000	40,000
	Roof	Install new safety treads at roof perimeter for safety	26.500	26 500
		and to accommodate window cleaners	20,500	26,500
		2019 Annual Actual Expense Total	333500	333500

This did not need to be done.

2020 Expense Summary

Year	Category	item Name	Expense	Amount
2020	Doors	East Entry ADA upgrade	2,550	2,550
	Garage	Re-surface (aluminum oxide) lower level ramps	7,141	7,141
	HVAC: Heating, Ventilation and Air Conditioning	Control air flow along 1st floor corridor	9,182	9,182
	Plumbing	Add plumbing to commercial spaces to provide for uninterrupted service during building-wide plumbig upgrade	51,009	51,009
		Additional plumbing prep for replacement of vertical plumbing (stacks) part I	20,404	20,404
	- Roof	North porches: remediate floors 2,3 and 4	4,591	7,652
	- 1001	Remediate 13th floor	3,061	7,052
	Security	Replace hallway fire alarms and electrical hook-up	10,222	10,222
		2020 Annual Expense Total	108,160	108,160

Objective is to mitigate odors from salon

2021 Expense Summary

Year	Category	item Name	Expense	Amount
2021	Electrical	Replace hallway sub-panel	54,120	58,283
	Electrical	Replace sub-panel in ECC (Electrical) room	4,163	30,203
	Elevator	Replace flooring	3,122	3,122
		Additional plumbing prep for replacement of vertical plumbing (stacks) part II	72,854	
	Plumbing	Update and replace horizontal plumbing on 12th floor	15,612	104,078
		Additional plumbing: prep for stacks replacement part	15,612	
	Roof	Roof anchor 2-year certification testing	5,309	5,309
	·	2021 Annual Expense Total	170,792	170,792

2022 Expense Summary				
Year	Category	item Name	Expense	Amount
2022	Architectural Interior: Paint and Seal	Paint 1st floor hallway	3,238	3,238
	Doors: Door: South Main Entry- Remedial work	Regularly scheduled maintenance on main entry door	549	549
	Miscellaneous: Repair & Renew	Security Cameras	5,309	13,803
	- iviiscellarieous, kepali & keriew	Key/ Fob/ Entry Guard System	8,494	
	Plumbing	Replace Risers and repair interiors part I	138,032	138,032
	Consults.	Security: Lighting- exterior	8,000	20.054
	Security	Garage: Replace or Repair the Roll-up Gates	31,854	39,854
	_	2022 Annual Expense Total	195,476	195,476

12/12/19 2016_2025_reserves_expenses.xlsx

2023 Expense Summary

Year	Category	item Name	Expense	Amount
2023	Electrical: Maintain & Repair	Generic need for repairs	32,496	32,496
	Plumbing	Replace Risers and repair interiors part II	173,314	173,314
	Roof	Roof anchor 2-year certification testing	5,309	5,309
		2023 Annual Expense Total	205,810	205,810

2024 Expense Summary

Year	Category	item Name	Expense	Amount
2024	Elevator: Replace Heat Pump	Regularly scheduled replacement	9,946	9,946
	Plumbing	Replace Risers and repair interiors part III	209,965	209,965
		2024 Annual Expense Total	219,911	219,911

2025 Expense Summary

Year	Category	item Name	Expense	Amount
2025	Boiler (Hot Water)	Replace Key Parts	37,204	37,204
	Plumbing	Replace Risers and repair interiors part IV	248,025	248,025
	Roof	Roof anchor 2-year certification testing	5,525	5,525
		2025 Annual Expense Total	290,754	290,754