Willamette Towers HOA- Reserves Study

1313 Lincoln Street Eugene Oregon 97401

February 3, 2018

Summary of Financial Assumptions

A complete reserves report was prepared for the year 2016. Updates are made yearly. A report is prepared every 5 or 6 years with a new starting year.

Summary of Financial Information

The study is based on the calendar year.

Funding Study Length: 30 Years

Number of Dues Paying Members- 91. Unit 206- a 92nd unit- is owned by Willamette Towers.

Reserve Balance as of January 1, 2018: \$176,324.

An annual inflation rate and tax considerations are not used in this report.

HOA dues include contributions to the reserves account. The contributions are usually set as part of the Annual Budget process.

Reserve Study Assumptions Include:

Cost estimates and financial information provided by this report are accurate and current. Sufficient comprehensive property insurance exists to protect Willamette Towers and the reserves from insurable risks such as fire, property liability, or vandalism.

This study entails plans to continue to maintain the existing common areas and amenities.

Study Method

A "Component" method is used. In the Full Reserves Report are details of the yearly contribution to any given item, or component, as refered to in the By-laws item 5.4 (b):

5.4 Special Assessments

(b) Reserve Trust Funds. In establishing reserves for the maintenance, repair or replacement of the common elements, the board of directors shall by resolution establish one or more trust funds for the maintenance, repair or replacement of specific items, in which case the board shall either designate part of the regular assessment or establish separate assessments for such purposes. The proceeds therefrom shall be held in such trust funds and used only for the designated maintenance, repairs or replacements.

The present cost of every reserve item has been estimated using past known costs, estimates and/or bids from contractors, amounts derived from study of reserves studies by other local HOA's, or cost estimating references available online.

In addition, every reserve item has been given an estimated remaining useful life and an estimated useful life when new.

Beginning around 2010, Software from AFI is used to prepare the report- information available at:

http://www.afiprofessional.com

The Full Reserves Report allows review of each reserve item in detail.

Summary of Findings

Estimated reserve item expenses are based upon preservation of existing improvements. The attached funding study is limited in scope to those expense items listed in the attached "Willamette Towers HOA Reserve Study Expense Items".

- Expense items which have an expected life of more than 30 years are included in this reserve study if payment for these items occurs within the 30-year study envelope. Otherwise, items are included when they come into the 30-year scope.
- Of primary concern is the preservation of a positive funding balance with funds sufficient to meet projected expenses throughout the study life.
- Based upon the attached funding study, the Member monthly fees will realize this goal. The professionals who designed the software for this study recommend that the ideal % funded is around 70%. This funds all items at a reasonable amount and allows for emergencies.

Out of Scope:

The elevators, considered to have a 35-year life and renovated in 2015, will come into scope (be included as a future reserves expense) in 2020 at a cost of \$350,000.

The exterior fencing, installed in 2005 and with a 50-year life, will come into scope in 2025 at a cost of \$50,000.

Prepared by

This report was prepared by John Rose, a resident of Willamette Towers. He was first involved with the Reserves Study done professionally by Robert Huntley in 2005 - 2006. The work is reviewed yearly by the office staff, the budget committee and other committees responsible for the types of expenses included in the reserves. Our office staff has a thorough understanding of the report and will answer your questions.

Understanding the Reserves Report

- The financial state of the reserves is most easily seen on the 1-page Cash Flow Analysis.

 Columns include the income (Annual Dues), the expenses total, and the reserves amount available at the end of each year.
- The column "% Funded" is important. This shows what percent of funding is actually available to pay for each year's share of every item in the reserves. For example, if a \$10,000 item with a 10-year repeating life has just been completed, the first year will have a funding need of \$1,000. Thus, a \$10,000 item will be fully funded in year 1 if \$1,000 (not \$10,000) is available in the reserves. Year 2, the amount would be \$2,000, etc.
- In 2005, reserves were very low; many high-priced items have been maintained, repaired or replaced since that time. The reserves have, for the most part, been adequate to make

- payments. There has not been the build-up of reserves one would need to raise the "% Funded."
- The garage upper deck remediation planned for 2019 will largely deplete the reserves, as have other large-ticket expenditures when performed, such as the elevator re-build and the boiler replacement.
- Reviewing the Cash Flow page, one can see that these large expenditures taper off after 2019 and the "% Funded" grows- a healthy situation.

Items to be considered...

- A wild card is what will be the plumbing needs of the building. It is hoped that the building-wide "blow-down" of 2018 will allay plumbing problems for 5 years. In anticipation of future needs, contributions of approximately \$20,000 per year are made to the reserves to handle spot fixes. It is estimated that pipe replacement throughout the building and related work could cost from 1.5 to over 2 million dollars- this is not scheduled and does not appear as a reserves item.
- Window washing has been postponed repeatedly because companies feel our roof poses an unsafe condition for workers. It is a problem in search of a solution.
- An item not included in the report is the front awning- whether to maintain (costs not ascertained), remove, or replace when necessary. Complete removal is an option, as the awning is not an original feature of the building.
- An internal cooling system once operated to cool at least some of the commercial spaces but it no longer functions. Repairing or replacing this has never been addressed. Cooling is now provided with typical window-mount air conditioners.

Final Notes

The Cash Flow page shows the contributions to the reserves being lessened in future years. This prevents the "% Funded" illogically growing beyond 100%. In fact, items coming into scope and other un-addressed items will most likely mean that this will not occur.

At the end of the report are items planned for the next few years explained in detail. While the reserves report provides basic planning, practical experience has taught that the details and timing are fluid and changing, year-by-year.

WT 2018 Reserve Study Expense Item Summary

			,	eni Summary								
Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacemen t Cost	Raw Annual Payment	Repeating Item?						
Architectural Exterior: Paint and Maintain												
Seal exterior seams and joints	\$ 0.00	9 Years	15 Years	\$ 0	\$ 0.00	No						
Seal Aggregate Panels	\$ 0.00	9 Years	15 Years	\$ 0	\$ 0.00	No						
Maintain brick: point up, clean and seal	\$ 0.00	9 Years	15 Years	\$ 0	\$ 0.00	No						
Paint Building Exterior	\$ 124,840	9 Years	15 Years	\$ 124,840	\$ 12,484	Yes						
Paint Garage	\$ 15,316	9 Years	15 Years	\$ 15,316	\$ 1,532	Yes						
Wash the Building	\$ 0.00	15 Years	15 Years	\$ 0	\$ 0.00	No						
Wash the Garage	\$ 0.00	15 Years	15 Years	\$ 0	\$ 0.00	No						
		Architectural Ir	nterior: Floorir	ng								
Flooring: Hallway Carpets- Replace	\$ 39,614	0 Years	10 Years	\$ 39,614	\$ 39,614	Yes						
Flooring: Linoleum- North Hallway	\$ 4,869	0 Years	10 Years	\$ 4,869	\$ 4,869	Yes						
Flooring: Lobby and East Entry	\$ 11,750	15 Years	24 Years	\$ 11,750	\$ 734	Yes						
		Architectural Ir	nterior: Lightir	ıg								
Lighting: North Hallway- Renew	\$ 1,760	10 Years	10 Years	\$ 1,760	\$ 160	Yes						
Lighting: Residence Floors- Renew	\$ 10,768	1 Years	10 Year	\$ 10,768	\$ 5,384	Yes						
	Archite	ectural Interior: L	obby & Office	Remodel								
Lobby & Office Remodel	\$ 18,227	15 Years	20 Years	\$ 18,227	\$ 1,139	Yes						
Lobby Remodel: Work by Others	\$ 0.00	15 Years	20 Years	\$ 0	\$ 0.00	No						
	A	rchitectural Inter	rior: Paint and	Seal								
Paint Residential Hallways	\$ 51,180	8 Years	12 Years	\$ 51,180	\$ 5,687	Yes						
Paint 1st Floor Hallway	\$ 3,050	0 Years	4 Years	\$ 3,050	\$ 3,050	Yes						
Paint Stairways	\$ 24,000	8 Years	12 Years	\$ 24,000	\$ 2,667	Yes						
Paint Residential Floor Maintenance Doors: Elevators, Stairs, Janitor & Garbage	\$ 16,500	4 Years	6 Years	\$ 16,500	\$ 3,300	Yes						
		Roiler /L	lot Water)									
Boiler: Replace Key Parts	\$ 30,562	11 Years	12 Years	\$ 30,562	\$ 2,547	Yes						

WT 2018 Funding Study Expense Item Summary - Continued

Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacemen t Cost	Raw Annual Payment	Repeating Item?
Door: South Main Entry	\$ 9,483	0 Years	25 Years	\$ 9,483	\$ 9,483	No
Door: East Entry ADA upgrade	\$ 4,000	2 Years	25 Years	\$ 4,000	\$ 1,333	No
Door: North Entry ADA Upgrade	\$ 4,000	2 Years	25 Years	\$ 4,000	\$ 1,333	No
Door: North Stairway Entrance	\$ 3,429	0 Years	25 Years	\$ 3,429	\$ 3,429	No
Doors: Stairway- Floors 2 and 3	\$ 5,292	0 Years	30 Years	\$ 5,292	\$ 5,292	No
Door: South Main Entry- Remedial Work	\$ 517	1 Years	30 Year	\$ 517	\$ 259	No
		Elec	ctrical			
Electrical: Replace sub-	# 0.00			# 0	# 0.00	NI-
panel in ECC Room	\$ 0.00	5 Years	35 Years	\$ 0	\$ 0.00	No
Electrical: Replace hallway sub-panels	\$ 0.00	5 Years	35 Years	\$ 0	\$ 0.00	No
Electrical: Maintain and Repair	\$ 15,000	7 Years	10 Years	\$ 15,000	\$ 1,875	Yes
		Ele	vator			
Elevator Consultants	\$ 7,500	35 Years	35 Years	\$ 7,500	\$ 259	No
Elevator: Work by Others	\$ 11,416	35 Years	35 Years	\$ 11,416	\$ 394	No
Elevator: Refurbish- new interiors	\$ 9,000	5 Years	6 Years	\$ 9,000	\$ 1,500	Yes
Elevator A: Replace Mechanical	\$ 178,820	35 Years	35 Years	\$ 178,820	\$ 6,166	No
Elevator B: Replace Mechanical	\$ 178,820	35 Years	35 Years	\$ 178,820	\$ 6,166	No
Elevator: Replace Heat Pump	\$ 2,100	14 Years	15 Years	\$ 2,100	\$ 140	Yes
		Ga	rage			
Garage: General Upkeep	\$ 0.00	5 Years	20 Years	\$0	\$ 0.00	No
Garage: Upper Deck Resurface	\$ 275,000	3 Years	50 Years	\$ 275,000	\$ 68,750	Yes
Upper Deck Remediation	\$ 10,550	1 Years	31 Year	\$ 10,550	\$ 5,275	No
		Miscellanceur	s: Major Items			
Paving: Asphalt Seal Coat	\$ 1,970	6 Years	6 Years	\$ 1,970	\$ 281	Yes
Paving: North near building- Asphalt Repair and Seal	\$ 1,270	1 Years	12 Year	\$ 1,270	\$ 635	Yes

WT 2018 Funding Study Expense Item Summary - Continued

Paving: North side concrete paving Paving: South- Asphalt Repair and Seal Ventilation: Clean North side vents	Current Cost When New \$ 0.00 \$ 700	Estimated Remaining Life 3 Years 1 Years 6 Years	Expected Life When New 30 Years 12 Year 15 Years	First Replacemen t Cost \$ 0 \$ 700 \$ 25,000	Raw Annual Payment \$ 0.00 \$ 350 \$ 3,571	Repeating Item? No Yes Yes
Ventilation: Clean South Side Ventilation/North Side: Clean One Floor	\$ 15,000 \$ 5,000	6 Years 5 Years	15 Years 20 Years	\$ 15,000 \$ 5,000	\$ 2,143 \$ 833	Yes No
		Miscellaneous: F	Penair and Por	1ew		
Architectural Exterior: Landscape- Prune Trees	\$ 2,000	8 Years	50 Years	\$ 2,000	\$ 222	Yes
Architectural Exterior: Landscape- Repair Sprinkler Lines	\$ 500	8 Years	50 Years	\$ 500	\$ 55.56	No
Architectural Exterior: Replace Glass: Commercial, etc.	\$ 1,000	8 Years	50 Years	\$ 1,000	\$ 111	No
Architectural Interior: Ceilings: Repair and Renew	\$ 3,000	8 Years	50 Years	\$ 3,000	\$ 333	No
Architectural Interior: Flooring: Commercial Spaces	\$ 4,500	8 Years	50 Years	\$ 4,500	\$ 500	No
Architectural Interior: Flooring: Mats	\$ 504	1 Years	7 Year	\$ 504	\$ 252	Yes
Architectural Interior: Metal Handrails	\$ 1,750	8 Years	50 Years	\$ 1,750	\$ 194	No
Doors: Commercial	\$ 3,000	8 Years	50 Years	\$ 3,000	\$ 333	No
Doors: Exterior- Replace	\$ 3,000	8 Years	50 Years	\$ 3,000	\$ 333	No
Doors: Interior	\$ 5,970	8 Years	50 Years	\$ 5,970	\$ 663	No
MIscellaneous: Paving: Repair Sidewalks	\$ 3,037	8 Years	50 Years	\$ 3,037	\$ 338	No
Miscellaneous: Office Equipment	\$ 1,500	8 Years	9 Years	\$ 1,500	\$ 167	Yes
Miscellaneous: Office- Replace Furniture	\$ 1,500	8 Years	50 Years	\$ 1,500	\$ 167	No
Miscellaneous: Parking- Bicycle Racks	\$ 1,050	8 Years	50 Years	\$ 1,050	\$ 117	No
Roof: Awning Replace Roof: Awning- Repair	\$ 9,500	8 Years	50 Years	\$ 9,500	\$ 1,056	No
Mounting Nepall	\$ 2,500	8 Years	8 Years	\$ 2,500	\$ 278	No

WT 2018 Funding Study Expense Item Summary - Continued

				imary - Continue		
Reserve Items	Current Cost When New	Estimated Remaining Life	Expected Life When New	First Replacemen t Cost	Raw Annual Payment	Repeating Item?
Roof: Seal Patios (Roofs) and North Porches	\$ 0.00	8 Years	10 Years	\$ 0	\$ 0.00	No
Security: Cameras	\$ 5,000	6 Years	8 Years	\$ 5,000	\$ 714	No
Security: Key / Fob / Entry Guard System	\$ 2,351	0 Years	7 Years	\$ 2,351	\$ 2,351	No
Security: Lighting- Exterior	\$ 8,000	6 Years	10 Years	\$ 8,000	\$ 1,143	No
		Plui	mbing			
Plumbing Replace Stack Valves Phase 2	\$ 17,915	0 Years	30 Years	\$ 17,915	\$ 17,915	No
Plumbing Replace Stack Valves- Phase 3	\$ 36,542	1 Years	30 Year	\$ 36,542	\$ 18,271	No
Plumbing Phase 3: Asbestos abatement	\$ 3,946	1 Years	30 Year	\$ 3,946	\$ 1,973	No
Plumbing Remediation	\$ 82,000	2 Years	31 Years	\$ 82,000	\$ 27,333	No
Pipe Repair- Manifold Line	\$ 5,100	1 Years	31 Year	\$ 5,100	\$ 2,550	No
Plumbing: General Upgrade	\$ 150,000	7 Years	5 Years	\$ 150,000	\$ 18,750	Yes
		R	loof			
Roof: Consultant	\$ 0.00	10 Years	21 Years	\$ 0	\$ 0.00	No
Roof: Building Roof and Flat Roofs (4)	\$ 75,000	10 Years	21 Years	\$ 75,000	\$ 6,818	Yes
Roof: Re-Roof 2nd Floor Patio	\$ 28,393	15 Years	20 Years	\$ 28,393	\$ 1,775	Yes
Roof: East Portico- Rebuild & Re-Roof	\$ 5,364	0 Years	9 Years	\$ 5,364	\$ 5,364	Yes
North Porches- Remediate	\$ 18,000	5 Years	31 Years	\$ 18,000	\$ 3,000	No
		Sec	curity			
Security: Garage Roll-up Gates	\$ 30,000	6 Years	18 Years	\$ 30,000	\$ 4,286	Yes
Security: Fencing	\$ 58,897	40 Years	50 Years	\$ 58,897	\$ 1,963	No
		Win	dows			
Windows: Replace Frames and Glass	\$ 0.00	5 Years	30 Years	\$ 0	\$ 0.00	No

Raw Annual Payments do not include earned interest, tax adjustments or salvage.

Months Remaining in Calendar Year 2016: 12

Expected annual inflation: 0.00%

WT 2018 Funding Study Expense Item Summary - Continued

Interest earned on reserve funds: 0.00%

Initial Reserve: \$ 119,588

WT 2018 Reserve Study Expense Item Listing

			Current	Estimated	Expected			
Reserve Items	Unit Cost	No Units	Cost When New	Remaining Life	Life When New	Calendar Year	Estimated Future Cost	Raw Annual Payment
		Ar	chitectural E	xterior: Paint	and Maintair	1		
Seal exterior seams and joints	\$ 0.00 ea	1	\$ 0	9 Years	15 Years	2025	\$ 0	\$ 0.00
Seal Aggregate Panels	\$ 0.00 ea	1	\$ 0	9 Years	15 Years	2025	\$0	\$ 0.00
Maintain brick: point up, clean and seal	\$ 0.00 ea	1	\$0	9 Years	15 Years	2025	\$ 0	\$ 0.00
				9 Years		2025	\$ 124,840	\$ 12,484.00
Paint Building Exterior	\$ 124,840 ea	1	\$ 124,840	45.7/	15 Years	2040	\$ 124,840	\$ 8,322.67
Exterior				15 Years		2055	\$ 124,840	\$ 8,322.67
				9 Years		2025	\$ 15,316	\$ 1,531.60
Paint Garage	\$ 15,316 ea	1	\$ 15,316	15 Years	15 Years	2040	\$ 15,316	\$ 1,021.07
				15 feats		2055	\$ 15,316	\$ 1,021.07
Wash the Building	\$ 0.00 ea	1	\$ 0	15 Years	15 Years	2031	\$0	\$ 0.00
Wash the Garage	\$ 0.00 ea	1	\$ 0	15 Years	15 Years	2031	\$ 0	\$ 0.00
			Architectu	ıral Interior: F	looring			
				0 Years		2016	\$ 39,614	\$ 39,614.40
Flooring:					l	2026	\$ 39,614	\$ 3,961.44
Hallway	\$ 5.24 / ft ²	7560 ft²	\$ 39,614		10 Years	2036	\$ 39,614	\$ 3,961.44
Carpets- Replace				10 Years		2046	\$ 39,614	\$ 3,961.44
•						2056	\$ 39,614	\$ 3,961.44
				0 Years		2016	\$ 4,869	\$ 4,868.64
Flooring:						2026	\$ 4,869	\$ 486.86
Linoleum-	\$ 8.82 / ft ²	552 ft²	\$ 4,869	40.14	10 Years	2036	\$ 4,869	\$ 486.86
North Hallway				10 Years		2046	\$ 4,869	\$ 486.86
						2056	\$ 4,869	\$ 486.86
Flooring: Lobby	Ф от оо / «»	470 (12	¢ 44 750	15 Years	24.7/-	2031	\$ 11,750	\$ 734.37
and East Entry	\$ 25.00 / ft ²	470 ft ²	\$ 11,750	24 Years	24 Years	2055	\$ 11,750	\$ 489.58
			Architectu	ıral Interior: L	ighting			
						2026	\$ 1,760	\$ 160.00
Lighting: North	\$ 220 ea	8	\$ 1,760	10 Years	10 Years	2036	\$ 1,760	\$ 176.00
Hallway- Renew						2046	\$ 1,760	\$ 176.00

WT 2018 Reserve Study Expense Item Listing - Continued

		VV 1 2010 1	Reserve Study	Expense item	. Lioung Cor			
Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Calendar Year	Estimated Future Cost	Raw Annual Payment
Lighting: North	\$ 220 ea	8	\$ 1,760	10 Years	10 Years	2056	\$ 1,760	\$ 176.00
				1 Year		2017	\$ 10,768	\$ 5,383.80
Lighting:					1	2027	\$ 10,768	\$ 1,076.76
Residence	\$ 99.70 ea	108	\$ 10,768		10 Years	2037	\$ 10,768	\$ 1,076.76
Floors- Renew				10 Year		2047	\$ 10,768	\$ 1,076.76
						2057	\$ 10,768	\$ 1,076.76
		Arch	itectural Inte	rior: Lobby &	Office Remo	del		
Lobby & Office		1		15 Years		2031	\$ 18,227	\$ 1,139.19
Remodel	\$ 18,227 ea	1	\$ 18,227	20 Years	20 Years	2051	\$ 18,227	\$ 911.35
Lobby Remodel: Work by Others	\$ 0.00 ea	1	\$ 0	15 Years	20 Years	2031	\$0	\$ 0.00
			Architectural	Interior: Pain	t and Seal			
Paint				8 Years		2024	\$ 51,180	\$ 5,686.67
Residential	\$ 4,265 ea	12	\$ 51,180	40.77	12 Years	2036	\$ 51,180	\$ 4,265.00
Hallways				12 Years		2048	\$ 51,180	\$ 4,265.00
				0 Years		2016	\$ 3,050	\$ 3,050.00
						2020	\$ 3,050	\$ 762.50
						2024	\$ 3,050	\$ 762.50
						2028	\$ 3,050	\$ 762.50
Paint 1st Floor Hallway	\$ 3,050 ea	1	\$ 3,050	4 \/	4 Years	2032	\$ 3,050	\$ 762.50
Tianway				4 Years		2036	\$ 3,050	\$ 762.50
						2040	\$ 3,050	\$ 762.50
						2044	\$ 3,050	\$ 762.50
						2048	\$ 3,050	\$ 762.50
				8 Years		2024	\$ 24,000	\$ 2,666.67
Paint Stairways	\$ 1,000 ea	24	\$ 24,000	40.77	12 Years	2036	\$ 24,000	\$ 2,000.00
				12 Years		2048	\$ 24,000	\$ 2,000.00
Paint				4 Years		2020	\$ 16,500	\$ 3,300.00
Residential						2026	\$ 16,500	\$ 2,750.00
Floor Maintenance	, individual control of the control	\$ 16,500		6 Years	2032	\$ 16,500	\$ 2,750.00	
Doors:			6 Years		2038	\$ 16,500	\$ 2,750.00	
Elevators, Stairs, Janitor &						2044	\$ 16,500	\$ 2,750.00

WT 2018 Reserve Study Expense Item Listing - Continued

				Expense item				
Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Calendar Year	Estimated Future Cost	Raw Annual Payment
Paint	\$ 1,375 ea	12	\$ 16,500	6 Years	6 Years	2050	\$ 16,500	\$ 2,750.00
			Deil	o (1154 M/s45)				
			ВОП	er (Hot Water)		2027	¢ 20 500	P.O. F.4C. 0.2
Boiler: Replace	Ф 45 OO4 оо		Ф 20 FC2	11 Years	10 Vaara	2027	\$ 30,562	\$ 2,546.83
Key Parts	\$ 15,281 ea	2	\$ 30,562	12 Years	12 Years	2039 2051	\$ 30,562	\$ 2,546.83
						2051	\$ 30,562	\$ 2,546.83
				Doors				
Door: South Main Entry	\$ 9,483 ea	1	\$ 9,483	0 Years	25 Years	2016	\$ 9,483	\$ 9,483.00
Door: East Entry ADA upgrade	\$ 4,000 ea	1	\$ 4,000	2 Years	25 Years	2018	\$ 4,000	\$ 1,333.33
Door: North Entry ADA Upgrade	\$ 4,000 ea	1	\$ 4,000	2 Years	25 Years	2018	\$ 4,000	\$ 1,333.33
Door: North Stairway Entrance	\$ 3,429 ea	1	\$ 3,429	0 Years	25 Years	2016	\$ 3,429	\$ 3,429.00
Doors: Stairway- Floors 2 and 3	\$ 2,646 ea	2	\$ 5,292	0 Years	30 Years	2016	\$ 5,292	\$ 5,292.00
Door: South Main Entry- Remedial Work	\$ 517 ea	1	\$ 517	1 Year	30 Years	2017	\$ 517	\$ 258.50
				Electrical				
Electrical: Replace sub- panel in ECC Room	\$ 0.00 ea	1	\$0	5 Years	35 Years	2021	\$0	\$ 0.00
Electrical: Replace hallway sub- panels	\$ 0.00 ea	13	\$ 0	5 Years	35 Years	2021	\$0	\$ 0.00
				7 Years		2023	\$ 15,000	\$ 1,875.00
Electrical: Maintain and	\$ 15,000 ea	1	\$ 15,000		10 Years	2033	\$ 15,000	\$ 1,500.00
Repair	φ 15,000 ea	'	φ 15,000	10 Years	TO TEALS	2043	\$ 15,000	\$ 1,500.00
						2053	\$ 15,000	\$ 1,500.00

WT 2018 Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Calendar Year	Estimated Future Cost	Raw Annual Payment
				Elevator				
Elevator Consultants	\$ 7,500 ea	1	\$ 7,500	35 Years	35 Years	2051	\$ 7,500	\$ 258.62
Elevator: Work by Others	\$ 11,416 ea	1	\$ 11,416	35 Years	35 Years	2051	\$ 11,416	\$ 393.66
				5 Years		2021	\$ 9,000	\$ 1,500.00
					I	2027	\$ 9,000	\$ 1,500.00
Elevator:	A. 500				2.1/	2033	\$ 9,000	\$ 1,500.00
Refurbish- new interiors	\$ 4,500 ea	2	\$ 9,000	6 Years	6 Years	2039	\$ 9,000	\$ 1,500.00
intolloro						2045	\$ 9,000	\$ 1,500.00
						2051	\$ 9,000	\$ 1,500.00
Elevator A: Replace Mechanical	\$ 178,820 ea	1	\$ 178,820	35 Years	35 Years	2051	\$ 178,820	\$ 6,166.21
Elevator B: Replace Mechanical	\$ 178,820 ea	1	\$ 178,820	35 Years	35 Years	2051	\$ 178,820	\$ 6,166.21
Elevator:				14 Years		2030	\$ 2,100	\$ 140.00
Replace Heat	\$ 2,100 ea	1	\$ 2,100	45.77	15 Years	2045	\$ 2,100	\$ 140.00
Pump				15 Years		2060	\$ 2,100	\$ 140.00
		,		Garage				
Garage: General Upkeep	\$ 0.00 ea	1	\$ 0	5 Years	20 Years	2021	\$ 0	\$ 0.00
Garage: Upper				3 Years		2019	\$ 275,000	\$ 68,750.00
Deck Re- surface	\$ 275,000 ea	1	\$ 275,000	50 Years	50 Years	2069	\$ 275,000	\$ 5,500.00
Upper Deck Remediation	\$ 10,550 ea	1	\$ 10,550	1 Year	31 Years	2017	\$ 10,550	\$ 5,275.00
			Miscellar	neous: Major l	Items			
				•		2022	\$ 1,970	\$ 281.49
						2028	\$ 1,970	\$ 328.40
Paving: Asphalt						2034	\$ 1,970	\$ 328.40
Seal Coat	\$ 1.64 / ft ²	1200 ft ²	\$ 1,970	6 Years	6 Years	2040	\$ 1,970	\$ 328.40
						2046	\$ 1,970	\$ 328.40
					2052	\$ 1,970	\$ 328.40	

WT 2018 Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When	Calendar Year	Estimated Future Cost	Raw Annual Payment
			New	Lile	New			
Paving: North				1 Year		2017	\$ 1,270	\$ 635.00
near building-	\$ 1,270 ea	1	\$ 1,270		12 Years	2029	\$ 1,270	\$ 105.83
Asphalt Repair	ψ .,=. σ σω		V 1, 2 1 V	12 Year		2041	\$ 1,270	\$ 105.83
and Seal						2053	\$ 1,270	\$ 105.83
Paving: North side concrete paving	\$ 0.00 ea	1	\$ 0	3 Years	30 Years	2019	\$ 0	\$ 0.00
				1 Year		2017	\$ 700	\$ 350.00
Paving: South-						2029	\$ 700	\$ 58.33
Asphalt Repair and Seal	\$ 700 ea	1	\$ 700	12 Year	12 Years	2041	\$ 700	\$ 58.33
and Sear						2053	\$ 700	\$ 58.33
Ventilation:				6 Years		2022	\$ 25,000	\$ 3,571.43
Clean North	\$ 25,000 ea	1	\$ 25,000		15 Years	2037	\$ 25,000	\$ 1,666.67
side vents				15 Years		2052	\$ 25,000	\$ 1,666.67
Ventilation:				6 Years		2022	\$ 15,000	\$ 2,142.86
Clean South	\$ 15,000 ea	1	\$ 15,000		15 Years	2037	\$ 15,000	\$ 1,000.00
Side			·	15 Years		2052	\$ 15,000	\$ 1,000.00
Ventilation/North Side: Clean One Floor	\$ 5,000 ea	1	\$ 5,000	5 Years	20 Years	2021	\$ 5,000	\$ 833.33
			Miscellaneo	us: Repair an	d Renew			
Architectural Exterior:	\$ 2,000 ea	1	\$ 2,000	8 Years	50 Years	2024	\$ 2,000	\$ 222.22
Landscape- Prune Trees	ψ 2,000 oα	, i	Ψ 2,000	50 Years	00 10010	2074	\$ 2,000	\$ 40.00
Architectural Exterior: Landscape- Repair Sprinkler Lines	\$ 500 ea	1	\$ 500	8 Years	50 Years	2024	\$ 500	\$ 55.56
Architectural Exterior: Replace Glass: Commercial, etc.	\$ 1,000 ea	1	\$ 1,000	8 Years	50 Years	2024	\$ 1,000	\$ 111.11

WT 2018 Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Calendar Year	Estimated Future Cost	Raw Annual Payment		
Architectural Interior: Ceilings: Repair and Renew	\$ 3,000 ea	1	\$ 3,000	8 Years	50 Years	2024	\$ 3,000	\$ 333.33		
Architectural Interior: Flooring: Commercial Spaces	\$ 1,500 ea	3	\$ 4,500	8 Years	50 Years	2024	\$ 4,500	\$ 500.00		
				1 Year		2017	\$ 504	\$ 252.00		
						2024	\$ 504	\$ 72.00		
Architectural	\$ 504 ea	1	\$ 504		7 Years	2031	\$ 504	\$ 72.00		
Interior: Flooring: Mats	ъ 504 ea	ı	Φ 504	7 Year	7 rears	2038	\$ 504	\$ 72.00		
3						2045	\$ 504	\$ 72.00		
						2052	\$ 504	\$ 72.00		
Architectural Interior: Metal Handrails	\$ 1,750 ea	1	\$ 1,750	8 Years	50 Years	2024	\$ 1,750	\$ 194.44		
Doors: Commercial	\$ 3,000 ea	1	\$ 3,000	8 Years	50 Years	2024	\$ 3,000	\$ 333.33		
Doors: Exterior- Replace	\$ 3,000 ea	1	\$ 3,000	8 Years	50 Years	2024	\$ 3,000	\$ 333.33		
Doors: Interior	\$ 1,990 ea	3	\$ 5,970	8 Years	50 Years	2024	\$ 5,970	\$ 663.33		
Miscellaneous: Paving: Repair Sidewalks	\$ 7.50 / ft²	405 ft²	\$ 3,038	8 Years	50 Years	2024	\$ 3,038	\$ 337.50		
				8 Years		2024	\$ 1,500	\$ 166.67		
Miscellaneous: Office	¢ 1 500 oo	4	¢ 1 500		0 Veere	2033	\$ 1,500	\$ 166.67		
Equipment	\$ 1,500 ea	1	\$ 1,500	9 Years	9 Years	2042	\$ 1,500	\$ 166.67		
1 1 - 1						2051	\$ 1,500	\$ 166.67		
Miscellaneous: Office- Replace Furniture	\$ 1,500 ea	1	\$ 1,500	8 Years	50 Years	2024	\$ 1,500	\$ 166.67		
Miscellaneous: Parking- Bicycle Racks	\$ 210 ea	5	\$ 1,050	8 Years	50 Years	2024	\$ 1,050	\$ 116.67		
Roof: Awning Replace	\$ 9,500 ea	1	\$ 9,500	8 Years	50 Years	2024	\$ 9,500	\$ 1,055.56		

WT 2018 Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Calendar Year	Estimated Future Cost	Raw Annual Payment
Roof: Awning- Repair Mounting	\$ 2,500 ea	1	\$ 2,500	8 Years	8 Years	2024	\$ 2,500	\$ 277.78
Roof: Seal Patios (Roofs) and North Porches	\$ 0.00 ea	12	\$0	8 Years	10 Years	2024	\$0	\$ 0.00
Security: Cameras	\$ 5,000 ea	1	\$ 5,000	6 Years	8 Years	2022	\$ 5,000	\$ 714.29
Security: Key / Fob / Entry Guard System	\$ 2,351 ea	1	\$ 2,351	0 Years	7 Years	2016	\$ 2,351	\$ 2,351.00
Security: Lighting- Exterior	\$ 8,000 ea	1	\$ 8,000	6 Years	10 Years	2022	\$ 8,000	\$ 1,142.86
				Plumbing				
Plumbing Replace Stack Valves Phase 2	\$ 17,915 ea	1	\$ 17,915	0 Years	30 Years	2016	\$ 17,915	\$ 17,915.00
Plumbing Replace Stack Valves- Phase 3	\$ 36,542 ea	1	\$ 36,542	1 Year	30 Years	2017	\$ 36,542	\$ 18,271.00
Plumbing Phase 3: Asbestos abatement	\$ 3,946 ea	1	\$ 3,946	1 Year	30 Years	2017	\$ 3,946	\$ 1,973.00
Plumbing Remediation	\$ 82,000 ea	1	\$ 82,000	2 Years	31 Years	2018	\$ 82,000	\$ 27,333.33
Pipe Repair- Manifold Line	\$ 5,100 ea	1	\$ 5,100	1 Year	31 Years	2017	\$ 5,100	\$ 2,550.00
				7 Years		2023	\$ 150,000	\$ 18,750.00
						2028	\$ 150,000	\$ 30,000.00
Plumbing:	¢ 450 000 a-	4	¢ 150 000		F.Vee-	2033	\$ 150,000	\$ 30,000.00
General Upgrade	\$ 150,000 ea	1	\$ 150,000	5 Years	5 Years	2038	\$ 150,000	\$ 30,000.00
. •						2043	\$ 150,000	\$ 30,000.00
						2048	\$ 150,000	\$ 30,000.00
				Roof				
Roof: Consultant	\$ 0.00 ea	1	\$ 0	10 Years	21 Years	2026	\$0	\$ 0.00

WT 2018 Reserve Study Expense Item Listing - Continued

Reserve Items	Unit Cost	No Units	Current Cost When New	Estimated Remaining Life	Expected Life When New	Calendar Year	Estimated Future Cost	Raw Annual Payment
Roof: Building				10 Years		2026	\$ 75,000	\$ 6,818.18
Roof and Flat	\$ 75,000 ea	1	\$ 75,000	21 Years	21 Years	2047	\$ 75,000	\$ 3,571.43
Roofs (4)				21 16013		2068	\$ 75,000	\$ 3,571.43
Roof: Re-Roof	\$ 28,393 ea	1	\$ 28,393	15 Years	20 Years	2031	\$ 28,393	\$ 1,774.56
2nd Floor Patio	ў 20,393 ea	l l	φ 20,393	20 Years	20 16415	2051	\$ 28,393	\$ 1,419.65
				0 Years		2016	\$ 5,364	\$ 5,364.00
Roof: East						2025	\$ 5,364	\$ 596.00
Portico-Rebuild	\$ 5,364 ea	1	\$ 5,364	9 Years	9 Years	2034	\$ 5,364	\$ 596.00
& Re-Roof				9 Years		2043	\$ 5,364	\$ 596.00
						2052	\$ 5,364	\$ 596.00
North Porches- Remediate	\$ 1,500 ea	12	\$ 18,000	5 Years	31 Years	2021	\$ 18,000	\$ 3,000.00
				Security				
				6 Years		2022	\$ 30,000	\$ 4,285.71
Security: Garage Roll-up	\$ 15,000 ea	2	\$ 30,000		18 Years	2040	\$ 30,000	\$ 1,666.67
Gates	+ 13,233 33	_	+ 23,233	18 Years		2058	\$ 30,000	\$ 1,666.67
Security: Fencing	\$ 58,897 ea	1	\$ 58,897	40 Years	50 Years	2056	\$ 58,897	\$ 1,963.23
				Windows				
Windows: Replace Frames and Glass	\$ 0.00 ea	1	\$ 0	5 Years	30 Years	2021	\$0	\$ 0.00

Raw Annual Payments do not include earned interest, tax adjustments or payments made with inital reserves.

Months Remaining in Calendar Year 2016: 12

Expected annual inflation: 0.00% Interest earned on reserve funds: 0.00% Initial Reserve: \$ 119,588

Present Costs

Category	Item Name	No Units	Unit Cost	Present Cost	Net Present Value
	Seal exterior seams and joints	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
	Seal Aggregate Panels	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
Architectural	Maintain brick: point up, clean and seal	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
Exterior: Paint and Maintain	Paint Building Exterior	1	\$ 124,840.00 ea	\$ 124,840.00	\$ 74,904.00
Walitalii	Paint Garage	1	\$ 15,316.00 ea	\$ 15,316.00	\$ 9,189.60
	Wash the Building	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
	Wash the Garage	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
	Architectural Exterior:	Paint and Ma	aintain Sub Total =	\$ 140,156.00	\$ 84,093.60
A malaita atumal	Flooring: Hallway Carpets- Replace	7560 ft ²	\$ 5.24 / ft ²	\$ 39,614.43	\$ 0.03
Architectural Interior: Flooring	Flooring: Linoleum- North Hallway	552 ft ²	\$ 8.82 / ft ²	\$ 4,868.65	\$ 0.01
	Flooring: Lobby and East Entry	470 ft ²	\$ 25.00 / ft²	\$ 11,750.01	\$ 7,343.76
	Architectura	al Interior: Flo	ooring Sub Total =	\$ 56,233.09	\$ 7,343.75
		,	,		
Architectural	Lighting: North Hallway- Renew	8	\$ 220.00 ea	\$ 1,760.00	\$ 1,760.00
Interior: Lighting	Lighting: Residence Floors- Renew	108	\$ 99.70 ea	\$ 10,767.60	\$ 1,076.76
	Architectura	al Interior: Lig	ghting Sub Total =	\$ 12,527.60	\$ 2,836.76
	T				
Architectural	Lobby & Office Remodel	1	\$ 18,227.00 ea	\$ 18,227.00	\$ 13,670.25
Interior: Lobby & Office Remodel	Lobby Remodel: Work by Others	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
	Architectural Interior: Lobby	& Office Rei	model Sub Total =	\$ 18,227.00	\$ 13,670.25
		I			
	Paint Residential Hallways	12	\$ 4,265.00 ea	\$ 51,180.00	\$ 34,120.00
Architectural	Paint 1st Floor Hallway	1	\$ 3,050.00 ea	\$ 3,050.00	\$ 0.00
Interior: Paint and	Paint Stairways	24	\$ 1,000.00 ea	\$ 24,000.00	\$ 16,000.00
Seal	Paint Residential Floor Maintenance Doors: Elevators, Stairs, Janitor & Garbage	12	\$ 1,375.00 ea	\$ 16,500.00	\$ 11,000.00
	Architectural Inter			\$ 94,730.00	\$ 61,120.00

Present Costs - Continued

Category	Item Name	No Units	Unit Cost	Present Cost	Net Present Value
Boiler (Hot Water)	Boiler: Replace Key Parts	2	\$ 15,281.00 ea	\$ 30,562.00	\$ 28,015.17
	Door: South Main Entry	1	\$ 9,483.00 ea	\$ 9,483.00	\$ 0.00
	Door: East Entry ADA upgrade	1	\$ 4,000.00 ea	\$ 4,000.00	\$ 320.00
	Door: North Entry ADA Upgrade	1	\$ 4,000.00 ea	\$ 4,000.00	\$ 320.00
Doors	Door: North Stairway Entrance	1	\$ 3,429.00 ea	\$ 3,429.00	\$ 0.00
	Doors: Stairway- Floors 2 and 3	2	\$ 2,646.00 ea	\$ 5,292.00	\$ 0.00
	Door: South Main Entry- Remedial Work	1	\$ 517.00 ea	\$ 517.00	\$ 17.23
		[Doors Sub Total =	\$ 26,721.00	\$ 657.23
	Electrical: Replace sub-panel				
	in ECC Room	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
Electrical	Electrical: Replace hallway sub-panels	13	\$ 0.00 ea	\$ 0.00	\$ 0.00
	Electrical: Maintain and Repair	1	\$ 15,000.00 ea	\$ 15,000.00	\$ 10,500.00
		\$ 15,000.00	\$ 10,500.00		
	Elevator Consultants	1	\$ 7,500.00 ea	\$ 7,500.00	\$ 7,500.00
	Elevator: Work by Others	1	\$ 11,416.00 ea	\$ 11,416.00	\$ 11,416.00
	Elevator: Refurbish- new interiors	2	\$ 4,500.00 ea	\$ 9,000.00	\$ 7,500.00
Elevator	Elevator A: Replace Mechanical	1	\$ 178,820.00 ea	\$ 178,820.00	\$ 178,820.00
	Elevator B: Replace Mechanical	1	\$ 178,820.00 ea	\$ 178,820.00	\$ 178,820.00
	Elevator: Replace Heat Pump	1	\$ 2,100.00 ea	\$ 2,100.00	\$ 1,960.00
		Ele	evator Sub Total =	\$ 387,656.00	\$ 386,016.00
	Garage: General Upkeep	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
Garage	Garage: Upper Deck Resurface	1	\$ 275,000.00 ea	\$ 275,000.00	\$ 16,500.00
	Upper Deck Remediation	1	\$ 10,550.00 ea	\$ 10,550.00	\$ 340.32
		G	arage Sub Total =	\$ 285,550.00	\$ 16,840.32
	Paving: Asphalt Seal Coat	1200 ft²	\$ 1.64 / ft ²	\$ 1,970.43	\$ 1,970.43
Miscellaneous: Major Items	Paving: North near building- Asphalt Repair and Seal	1	\$ 1,270.00 ea	\$ 1,270.00	\$ 105.83

Present Costs - Continued

Category	Item Name	No Units	Unit Cost	Present Cost	Net Present Value
Miscellaneous: Major Items	Paving: North side concrete paving	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
	Paving: South- Asphalt Repair and Seal	1	\$ 700.00 ea	\$ 700.00	\$ 58.33
	Ventilation: Clean North side vents	1	\$ 25,000.00 ea	\$ 25,000.00	\$ 10,000.00
	Ventilation: Clean South Side	1	\$ 15,000.00 ea	\$ 15,000.00	\$ 6,000.00
	Ventilation/North Side: Clean One Floor	1	\$ 5,000.00 ea	\$ 5,000.00	\$ 1,250.00
	Miscellane	eous: Major I	tems Sub Total =	\$ 48,940.43	\$ 19,384.59
	Architectural Exterior: Landscape- Prune Trees	1	\$ 2,000.00 ea	\$ 2,000.00	\$ 320.00
	Architectural Exterior: Landscape- Repair Sprinkler Lines	1	\$ 500.00 ea	\$ 500.00	\$ 80.00
	Architectural Exterior: Replace Glass: Commercial, etc.	1	\$ 1,000.00 ea	\$ 1,000.00	\$ 160.00
	Architectural Interior: Ceilings: Repair and Renew	1	\$ 3,000.00 ea	\$ 3,000.00	\$ 480.00
	Architectural Interior: Flooring: Commercial Spaces	3	\$ 1,500.00 ea	\$ 4,500.00	\$ 720.00
	Architectural Interior: Flooring: Mats	1	\$ 504.00 ea	\$ 504.00	\$ 72.00
Miscellaneous:	Architectural Interior: Metal Handrails	1	\$ 1,750.00 ea	\$ 1,750.00	\$ 280.00
Repair and Renew	Doors: Commercial	1	\$ 3,000.00 ea	\$ 3,000.00	\$ 480.00
	Doors: Exterior- Replace	1	\$ 3,000.00 ea	\$ 3,000.00	\$ 480.00
	Doors: Interior	3	\$ 1,990.00 ea	\$ 5,970.00	\$ 955.20
	MIscellaneous: Paving: Repair Sidewalks	405 ft²	\$ 7.50 / ft ²	\$ 3,037.48	\$ 485.98
	Miscellaneous: Office Equipment	1	\$ 1,500.00 ea	\$ 1,500.00	\$ 1,333.33
	Miscellaneous: Office- Replace Furniture	1	\$ 1,500.00 ea	\$ 1,500.00	\$ 240.00
	Miscellaneous: Parking- Bicycle Racks	5	\$ 210.00 ea	\$ 1,050.00	\$ 168.00
	Roof: Awning Replace	1	\$ 9,500.00 ea	\$ 9,500.00	\$ 1,520.00
	Roof: Awning- Repair Mounting	1	\$ 2,500.00 ea	\$ 2,500.00	\$ 2,500.00
	Roof: Seal Patios (Roofs) and North Porches	12	\$ 0.00 ea	\$ 0.00	\$ 0.00

Present Costs - Continued

Category	Item Name	No Units	Unit Cost	Present Cost	Net Present Value
Miscellaneous:	Security: Cameras	1	\$ 5,000.00 ea	\$ 5,000.00	\$ 3,750.00
Repair and Renew	Security: Key / Fob / Entry Guard System	1	\$ 2,351.00 ea	\$ 2,351.00	\$ 0.00
	Security: Lighting- Exterior	1	\$ 8,000.00 ea	\$ 8,000.00	\$ 4,800.00
	Miscellaneous: R	epair and Re	enew Sub Total =	\$ 59,662.48	\$ 18,824.53
	Plumbing Replace Stack Valves Phase 2	1	\$ 17,915.00 ea	\$ 17,915.00	\$ 0.00
	Plumbing Replace Stack Valves- Phase 3	1	\$ 36,542.00 ea	\$ 36,542.00	\$ 1,218.07
Plumbing	Plumbing Phase 3: Asbestos abatement	1	\$ 3,946.00 ea	\$ 3,946.00	\$ 131.53
	Plumbing Remediation	1	\$ 82,000.00 ea	\$ 82,000.00	\$ 5,290.32
	Pipe Repair- Manifold Line	1	\$ 5,100.00 ea	\$ 5,100.00	\$ 164.52
	Plumbing: General Upgrade	1	\$ 150,000.00 ea	\$ 150,000.00	\$ 0.00
		Plur	nbing Sub Total =	\$ 295,503.00	\$ 6,804.44
	Roof: Consultant	1	\$ 0.00 ea	00.02	\$ 0.00
		1	\$ 0.00 ea	\$ 0.00	\$ 0.00
	Roof: Building Roof and Flat Roofs (4)	1	\$ 75,000.00 ea	\$ 75,000.00	\$ 35,714.29
Roof	Roof: Re-Roof 2nd Floor Patio	1	\$ 28,393.00 ea	\$ 28,393.00	\$ 21,294.75
	Roof: East Portico-Rebuild & Re-Roof	1	\$ 5,364.00 ea	\$ 5,364.00	\$ 0.00
	North Porches- Remediate	12	\$ 1,500.00 ea	\$ 18,000.00	\$ 2,903.22
			Roof Sub Total =	\$ 126,757.00	\$ 59,912.26
		Г	I		
Security	Security: Garage Roll-up Gates	2	\$ 15,000.00 ea	\$ 30,000.00	\$ 10,000.00
•	Security: Fencing	1	\$ 58,897.00 ea	\$ 58,897.00	\$ 58,897.00
		Se	ecurity Sub Total =	\$ 88,897.00	\$ 57,117.60
Windows	Windows: Replace Frames and Glass	1	\$ 0.00 ea	\$ 0.00	\$ 0.00
			Totals =	\$ 1,687,122.60	\$ 784,915.93

WT 2018 Funding Study Modified Cash Flow Analysis

Calendar Year	Annual Dues	Annual Interest	Salvage	Annual Expenses	Annual Income Tax	Net Reserve Funds	% Funded
2016	\$ 109,000			\$ 91,367		\$ 137,221	17.3%
2017	\$ 109,000			\$ 69,897		\$ 176,324	22.8%
2018	\$ 136,000			\$ 90,000		\$ 222,324	28.7%
2019	\$ 109,000			\$ 275,000		\$ 56,324	7.5%
2020	\$ 109,000			\$ 19,550		\$ 145,774	26.8%
2021	\$ 109,000			\$ 32,000		\$ 222,774	37.6%
2022	\$ 109,000			\$ 84,970		\$ 246,804	38.7%
2023	\$ 109,000			\$ 165,000		\$ 190,804	30.3%
2024	\$ 109,000			\$ 122,541		\$ 177,262	32.1%
2025	\$ 109,000			\$ 145,520		\$ 140,742	27.2%
2026	\$ 109,000			\$ 137,743		\$ 111,999	24.2%
2027	\$ 109,000			\$ 50,330		\$ 170,670	41.2%
2028	\$ 109,000			\$ 155,020		\$ 124,649	27.5%
2029	\$ 109,000			\$ 1,970		\$ 231,679	59.6%
2030	\$ 109,000			\$ 2,100		\$ 338,579	71.0%
2031	\$ 91,000			\$ 58,874		\$ 370,705	65.7%
2032	\$ 91,000			\$ 19,550		\$ 442,155	74.2%
2033	\$ 91,000			\$ 175,500		\$ 357,655	53.7%
2034	\$ 91,000			\$ 7,334		\$ 441,321	76.0%
2035	\$ 91,000					\$ 532,321	80.3%
2036	\$ 91,000			\$ 124,473		\$ 498,848	66.2%
2037	\$ 91,000			\$ 50,768		\$ 539,080	75.0%
2038	\$ 91,000			\$ 167,004		\$ 463,076	61.1%
2039	\$ 91,000			\$ 39,562		\$ 514,514	75.5%
2040	\$ 91,000			\$ 175,176		\$ 430,338	58.8%
2041	\$ 91,000			\$ 1,970		\$ 519,368	80.3%
2042	\$ 91,000			\$ 1,500		\$ 608,868	82.9%
2043	\$ 91,000			\$ 170,364		\$ 529,504	64.3%
2044	\$ 91,000			\$ 19,550		\$ 600,954	80.9%
2045	\$ 91,000			\$ 11,604		\$ 680,350	83.6%
2046	\$ 91,000			\$ 48,213		\$ 723,137	81.1%
2047	\$ 91,000			\$ 85,768		\$ 728,369	78.0%
2048	\$ 91,000			\$ 228,230		\$ 591,139	63.0%
2049	\$ 91,000					\$ 682,139	89.4%
Totals :	\$ 3,391,000	\$ 0	\$0	\$ 2,828,449	\$ 0		

¹ Cash Reserves minus Fully Funded Value

The cash distribution shown in this table applies to repair and replacement cash reserves only.

Basis of Funding Study - Modified Cash Flow

Cash reserves have been set to a minimum of \$ 0

Cash Flow has been modified with the forced Fixed Payments.

Study Life = 33 years Initial Reserve Funds = \$ 119,588.00 Final Reserve Value = \$ 682,138.94

WT_2018 Modified Reserve Dues Summary

Projected Dues by Month and by Calendar Year

			_	_		
Calendar Year	Member Monthly Operations Payment	Member Monthly Reserve Payment	Member Total Monthly Payment	Member Total Annual Payment	Monthly Reserve Payment	Annual Reserve Payment
2016	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2017	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2018	NA	\$ 124.54	\$ 124.54	\$ 1,494.51	\$ 11,333	\$ 136,000
2019	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2020	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2021	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2022	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2023	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2024	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2025	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2026	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2027	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2028	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2029	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2030	NA	\$ 99.82	\$ 99.82	\$ 1,197.80	\$ 9,083	\$ 109,000
2031	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2032	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2033	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2034	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2035	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2036	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2037	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2038	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2039	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2040	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2041	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2042	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2043	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2044	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2045	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2046	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2047	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2048	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000
2049	NA	\$ 83.33	\$ 83.33	\$ 1,000.00	\$ 7,583	\$ 91,000

WT 2018 Funding Study Payment Summary by Calendar Year - Continued

Dues Summary has been modified with forced Fixed Payments.

In the context of the Reserve Payment Summary, the "Annual Reserve Payment" corresponds

with the "Annual Revenue" in the Cash Flow report.

Operations Payments Include an annual inflation factor of 0.00%

Number of Payment Months in Calendar Year 2016: 12

Number of Years of Constant Payments: 1

No of Dues Paying Members: 91

WT 2018 Funding Unadjusted Revenue by Calendar Year

Item Name	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028
			F	Reserve Categ	ory : Archite	ectural Exteri	ior: Paint and	Maintain					
Seal exterior seams and joints	\$ 0	\$ O	\$ O	\$ O	\$ O	\$ O	\$ O	\$ 0	\$ O	\$ O			
Seal Aggregate Panels	\$ O	\$ O	\$ O	\$ O	\$ O	\$ O	\$ O	\$ 0	\$ O	\$ O			
Maintain brick: point up, clean and seal	\$ O	\$ O	\$ O	\$ O	\$ 0	\$ 0	\$ O	\$ 0	\$ O	\$ O			
Paint Building Exterior	\$ 12,484	\$ 12,484	\$ 12,484	\$ 12,484	\$ 12,484	\$ 12,484	\$ 12,484	\$ 12,484	\$ 12,484	\$ 12,484	\$ 8,323	\$ 8,323	\$ 8,323
Paint Garage	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,532	\$ 1,021	\$ 1,021	\$ 1,021
Wash the Building	\$ O	\$ 0	\$ 0	\$ 0	\$ 0	\$ 0	\$ O	\$ O	\$ O	\$ 0	\$ O	\$ O	\$ O
Wash the Garage	\$ 0	\$ 0	\$ 0	\$ 0	\$ 0	\$ 0	\$ O	\$ O	\$ O	\$ 0	\$ O	\$ O	\$ 0
Architectural Exterior: Paint and Maintain Subtotal :	\$ 14,016	\$ 14,016	\$ 14,016	\$ 14,016	\$ 14,016	\$ 14,016	\$ 14,016	\$ 14,016	\$ 14,016	\$ 14,016	\$ 9,344	\$ 9,344	\$ 9,344
				D	Catamamic	\	Intoviou. Flor						
Flagrica: Hallway				Reserve	Category : A	Architecturai	Interior: Floo	ring					
Flooring: Hallway Carpets- Replace	\$ 39,614	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961
Flooring: Linoleum- North Hallway	\$ 4,869	\$ 4 87	\$ 4 87	\$ 487	\$ 4 87	\$ 4 87	\$ 4 87	\$ 4 87	\$ 4 87	\$ 487	\$ 4 87	\$ 4 87	\$ 487
Flooring: Lobby and East Entry	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734	\$ 734
Architectural Interior: Flooring Subtotal:	\$ 45,217	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182	\$ 5,182
				Danamira	Catamami	1	Intovious I ind	- 4 i					
Lindstin on North				Reserve	Category : A	Arcnitecturai	Interior: Ligh	iting					
Lighting: North Hallway- Renew	\$ 160	\$ 160	\$ 160	\$ 160	\$ 160	\$ 160	\$ 160	\$ 160	\$ 160	\$ 160	\$ 160	\$ 176	\$ 176
Lighting: Residence Floors- Renew	\$ 5,384	\$ 5,384	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077
Architectural Interior: Lighting Subtotal:	\$ 5,544	\$ 5,544	\$ 1,237	\$ 1,237	\$ 1,237	\$ 1,237	\$ 1,237	\$ 1,237	\$ 1,237	\$ 1,237	\$ 1,237	\$ 1,253	\$ 1,253
			Res	serve Categor	y : Architect	ural Interior:	Lobby & Off	ice Remodel					

Unadjusted Revenue does not include earned interest, tax adjustments, or salvage.

Page 21 of 49 Pages

Copyright © IME 2001-2018

www.afiprofessional.com

			W1 2010	or unung c	maujusteu	Revenue	oy Calendal	i i cai - coi	mnueu				
Item Name	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028
Lobby & Office Remodel	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139
Lobby Remodel: Work by Others	\$ O	\$ 0	\$ O	\$ O	\$ 0	\$ 0	\$ O	\$ O	\$ 0	\$ 0	\$ 0	\$ 0	\$ 0
Architectural Interior: Lobby & Office Remodel Subtotal :	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139	\$ 1,139
				Reserve Ca	tegory · Arci	hitectural Int	erior: Paint a	nd Seal					
Paint Residential Hallways	\$ 5,687	\$ 5,687	\$ 5,687	\$ 5,687	\$ 5,687	\$ 5,687	\$ 5,687	\$ 5,687	\$ 5,687	\$ <i>4</i> ,265	\$ <i>4</i> ,265	\$ <i>4</i> ,265	\$ 4,265
Paint 1st Floor Hallway	\$ 3,050	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763
Paint Stairways	\$ 2,667	\$ 2,667	\$ 2,667	\$ 2,667	\$ 2,667	\$ 2,667	\$ 2,667	\$ 2,667	\$ 2,667	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000
Paint Residential Floor Maintenance Doors: Elevators, Stairs, Janitor & Garbage	\$ 3,300	\$ 3,300	\$ 3,300	\$ 3,300	\$ 3,300	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750
Architectural Interior: Paint and Seal Subtotal :	\$ 14,704	\$ 12,417	\$ 12,417	\$ 12,417	\$ 12,417	\$ 11,867	\$ 11,867	\$ 11,867	\$ 11,867	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778
				R	eserve Cate	gorv : Boiler	(Hot Water)						
Boiler: Replace Key Parts	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547
,						- 0-1	D						
Daam Cauth Main					Reserve	e Category :	Doors						
Door: South Main Entry	\$ 9,483												
Door: East Entry ADA upgrade	\$ 1,333	\$ 1,333	\$ 1,333										
Door: North Entry ADA Upgrade	\$ 1,333	\$ 1,333	\$ 1,333										
Door: North Stairway Entrance	\$ 3,429												

			_	o runung c	, , , , , , , , , , , , , , , , , , , ,								
Item Name	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028
Doors: Stairway- Floors 2 and 3	\$ 5,292												
Door: South Main Entry- Remedial Work	\$ 259	\$ 259											
Doors Subtotal :	\$ 21,129	\$ 2,925	\$ 2,666										
					_								
					Reserve	Category : E	ectrical			1			
Electrical: Replace sub-panel in ECC Room	\$ O	\$ 0	\$ 0	\$ 0	\$ O	\$ O							
Electrical: Replace hallway sub-panels	\$ O	\$ 0	\$0	\$ 0	\$ 0	\$ 0							
Electrical: Maintain and Repair	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
Electrical Subtotal :	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,875	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
					_								
		1	ſ		Reserve	Category : E		1		1			
Elevator Consultants							\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259
Elevator: Work by Others							\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394
Elevator: Refurbish- new interiors	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
Elevator A: Replace Mechanical							\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166
Elevator B: Replace Mechanical							\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166
Elevator: Replace Heat Pump	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140
Elevator Subtotal :	\$ 1,640	\$ 1,640	\$ 1,640	\$ 1,640	\$ 1,640	\$ 1,640	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625
					Reserve	Category :	Garage						
Garage: General Upkeep	\$ O	\$ 0	\$ 0	\$ 0	\$ 0	\$ 0							
Garage: Upper Deck Re-surface	\$ 68,750	\$ 68,750	\$ 68,750	\$ 68,750	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500

				or unumg c						ſ		ſ	
Item Name	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028
Upper Deck Remediation	\$ 5,275	\$ 5,275											
Garage Subtotal :	\$ 74,025	\$ 74,025	\$ 68,750	\$ 68,750	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500
				Reserv	ve Category	: Miscellane	ous: Major Ite	ems				ſ	
Paving: Asphalt Seal Coat	\$ 281	\$ 281	\$ 281	\$ 281	\$ 281	\$ 281	\$ 281	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328
Paving: North near building- Asphalt Repair and Seal	\$ 635	\$ 635	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106
Paving: North side concrete paving	\$ O	\$ O	\$ O	\$ O									
Paving: South- Asphalt Repair and Seal	\$ 350	\$ 350	\$ <i>5</i> 8	\$ <i>5</i> 8	\$ 58	\$ <i>5</i> 8	\$ 5 8	\$ 58	\$ 58	\$ 58	\$ <i>5</i> 8	\$ 58	\$ 58
Ventilation: Clean North side vents	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667
Ventilation: Clean South Side	\$ 2,143	\$ 2,143	\$ 2,143	\$ 2,143	\$ 2,143	\$ 2,143	\$ 2,143	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000
Ventilation/North Side: Clean One Floor	\$ 833	\$ 833	\$ 833	\$ 833	\$ 833	\$ 833							
Miscellaneous: Major Items Subtotal :	\$ 7,813	\$ 7,813	\$ 6,992	\$ 6,992	\$ 6,992	\$ 6,992	\$ 6,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159
				D	2-1	·		D					
				Reserve C	ategory : IVII	scellaneous	: Repair and	Renew					
Architectural Exterior: Landscape- Prune Trees	\$ 222	\$ 222	\$ 222	\$ 222	\$ 222	\$ 222	\$ 222	\$ 222	\$ 222	\$ 40	\$ 40	\$ 40	\$ 40
Architectural Exterior: Landscape- Repair Sprinkler Lines	\$ 56	\$ 56	\$ 56	\$ 56	\$ 56	\$ 56	\$ 56	\$ 56	\$ 56				
Architectural Exterior: Replace Glass: Commercial, etc.	\$ 111	\$ 111	\$ 111	\$ 111	\$ 111	\$ 111	\$ 111	\$ 111	\$ 111				

		2017		or unumg c	1	2021							
Item Name	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028
Architectural Interior: Ceilings: Repair and Renew	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333				
Architectural Interior: Flooring: Commercial Spaces	\$ 500	\$ 500	\$ 500	\$ 500	\$ 500	\$ 500	\$ 500	\$ 500	\$ 500				
Architectural Interior: Flooring: Mats	\$ 252	\$ 252	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72
Architectural Interior: Metal Handrails	\$ 194	\$ 194	\$ 194	\$ 194	\$ 194	\$ 194	\$ 194	\$ 194	\$ 194				
Doors: Commercial	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333				
Doors: Exterior- Replace	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333	\$ 333				
Doors: Interior	\$ 663	\$ 663	\$ 663	\$ 663	\$ 663	\$ 663	\$ 663	\$ 663	\$ 663				
MIscellaneous: Paving: Repair Sidewalks	\$ 338	\$ 338	\$ 338	\$ 338	\$ 338	\$ 338	\$ 338	\$ 338	\$ 338				
Miscellaneous: Office Equipment	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167
Miscellaneous: Office- Replace Furniture	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167				
Miscellaneous: Parking- Bicycle Racks	\$ 117	\$ 117	\$ 117	\$ 117	\$ 117	\$ 117	\$ 117	\$ 117	\$ 117				
Roof: Awning Replace	\$ 1,056	\$ 1,056	\$ 1,056	\$ 1,056	\$ 1,056	\$ 1,056	\$ 1,056	\$ 1,056	\$ 1,056				
Roof: Awning- Repair Mounting	\$ 278	\$ 278	\$ 278	\$ 278	\$ 278	\$ 278	\$ 278	\$ 278	\$ 278				
Roof: Seal Patios (Roofs) and North Porches	\$ O	\$ O	\$ O	\$ O	\$ 0	\$ 0	\$ O	\$ O	\$ O				
Security: Cameras	\$ 714	\$ 714	\$ 714	\$ 714	\$ 714	\$ 714	\$ 714						
Security: Key / Fob / Entry Guard System	\$ 2,351												

Item Name	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028
Security: Lighting- Exterior	\$ 1,143	\$ 1,143	\$ 1,143	\$ 1,143	\$ 1,143	\$ 1,143	\$ 1,143						
Miscellaneous: Repair and Renew Subtotal :	\$ 9,328	\$ 6,977	\$ 6,797	\$ 6,797	\$ 6,797	\$ 6,797	\$ 6,797	\$ 4,940	\$ 4,940	\$ 279	\$ 279	\$ 279	\$ 279
					Reserve (Category : Pl	umbing						
Plumbing Replace Stack Valves Phase 2	\$ 17,915												
Plumbing Replace Stack Valves- Phase 3	\$ 18,271	\$ 18,271											
Plumbing Phase 3: Asbestos abatement	\$ 1,973	\$ 1,973											
Plumbing Remediation	\$ 27,333	\$ 27,333	\$ 27,333										
Pipe Repair- Manifold Line	\$ 2,550	\$ 2,550											
Plumbing: General Upgrade	\$ 18,750	\$ 18,750	\$ 18,750	\$ 18,750	\$ 18,750	\$ 18,750	\$ 18,750	\$ 18,750	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000
Plumbing Subtotal :	\$ 86,792	\$ 68,877	\$ 46,083	\$ 18,750	\$ 18,750	\$ 18,750	\$ 18,750	\$ 18,750	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000
					Reserv	ve Category :	Roof						
Roof: Consultant	\$ O	\$ 0	\$ 0	\$ 0	\$ 0	\$0	\$ 0	\$ 0	\$ 0	\$ 0	\$ O		
Roof: Building Roof and Flat Roofs (4)	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 6,818	\$ 3,571	\$ 3,571
Roof: Re-Roof 2nd Floor Patio	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,775
Roof: East Portico- Rebuild & Re-Roof	\$ 5,364	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596
North Porches- Remediate	\$ 3,000	\$ 3,000	\$ 3,000	\$ 3,000	\$ 3,000	\$ 3,000							
Roof Subtotal :	\$ 16,957	\$ 12,189	\$ 12,189	\$ 12,189	\$ 12,189	\$ 12,189	\$ 9,189	\$ 9,189	\$ 9,189	\$ 9,189	\$ 9,189	\$ 5,942	\$ 5,942
					Reserve	Category : S	Security						
							,						

Item Name	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028
Security: Garage Roll- up Gates	\$ 4,286	\$ 4,286	\$ 4,286	\$ 4,286	\$ 4,286	\$ 4,286	\$ 4,286	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667
Security: Fencing											\$ 1,963	\$ 1,963	\$ 1,963
Security Subtotal:	\$ <i>4</i> ,286	\$ <i>4</i> ,286	\$ 4,286	\$ 4,286	\$ 4,286	\$ 4,286	\$ <i>4</i> ,286	\$ 1,667	\$ 1,667	\$ 1,667	\$ 3,630	\$ 3,630	\$ 3,630
					Reserve	Category : W	/indows						
Windows: Replace Frames and Glass	\$ 0	\$0	\$ 0	\$ 0	\$ O	\$ 0							
	. 1	. 1	. [. [. [. [. [. 1	. [
Total Revenue :	\$ 307,012	\$ 221,452	\$ 187,816	\$ 157,816	\$ 94,566	\$ 94,016	\$ 103,168	\$ 95,691	\$ 106,566	\$ 99,817	\$ 97,108	\$ 93,877	\$ 93,877

Item Name	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
			F	Reserve Cate	gory : Archi	tectural Exte	rior: Paint a	nd Maintain					
Seal exterior seams and joints													
Seal Aggregate Panels													
Maintain brick: point up, clean and seal													
Paint Building Exterior	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323
Paint Garage	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021
Wash the Building	\$ 0	\$ 0	\$ 0										
Wash the Garage	\$ 0	\$ 0	\$ 0										
Architectural Exterior: Paint and Maintain Subtotal :	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344
				D	- 0-1	A		·					
Election Helbury				Reserve	e Category :	Arcnitectura	ii interior: Fi	ooring					
Flooring: Hallway Carpets- Replace	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961
Flooring: Linoleum- North Hallway	\$ 4 87	\$ 487	\$ 4 87	\$ 4 87	\$ 4 87	\$ 4 87	\$ 4 87	\$ 4 87	\$ 487	\$ 4 87	\$ 4 87	\$ 4 87	\$ 4 87
Flooring: Lobby and East Entry	\$ 734	\$ 734	\$ 734	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490
Architectural Interior: Flooring Subtotal:	\$ 5,182	\$ 5,182	\$ 5,182	\$ 4,938	\$ 4,938	\$ 4 ,938	\$ 4,938	\$ 4 ,938	\$ 4,938	\$ 4,938	\$ 4,938	\$ 4,938	\$ 4,938
				Posory	e Category :	Architoctur	al Interior: Li	iahtina					
Lighting: North				Neser V	e Calegory .	Arcintecture	ii iiiterior. Li	grang					
Lighting: North Hallway- Renew	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176
Lighting: Residence Floors- Renew	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077
Architectural Interior: Lighting Subtotal:	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253
			Res	serve Catego	ory : Archited	ctural Interio	r: Lobby & C	Office Remod	lel				

			1		,	- TOVOITUO		1	1	1	T		1
Item Name	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Lobby & Office Remodel	\$ 1,139	\$ 1,139	\$ 1,139	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911
Lobby Remodel: Work by Others	\$ 0	\$ 0	\$ 0										
Architectural Interior: Lobby & Office Remodel Subtotal :	\$ 1,139	\$ 1,139	\$ 1,139	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$911	\$911	\$ 911	\$ 911
				Reserve C	ategory : Ard	chitectural Ir	nterior: Paint	t and Seal					
Paint Residential Hallways	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265	\$ 4,265
Paint 1st Floor Hallway	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763
Paint Stairways	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000
Paint Residential Floor Maintenance Doors: Elevators, Stairs, Janitor & Garbage	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750
Architectural Interior: Paint and Seal Subtotal :	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778
					Reserve Cate	egory : Boile	er (Hot Water	·)					
Boiler: Replace Key Parts	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547
					Reser	ve Category	: Doors						
Door: South Main Entry													
Door: East Entry ADA upgrade													
Door: North Entry ADA Upgrade													
Door: North Stairway Entrance													

					-	T TO TOTAL				1			
Item Name	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Doors: Stairway- Floors 2 and 3													
Door: South Main Entry- Remedial Work													
Doors Subtotal:													
					_	_							
	ſ				Reserve	Category :	Electrical		1				
Electrical: Replace sub-panel in ECC Room													
Electrical: Replace hallway sub-panels													
Electrical: Maintain and Repair	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
Electrical Subtotal :	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
					D	- 0-1							
						e Category :	ſ						
Elevator Consultants	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259
Elevator: Work by Others	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394
Elevator: Refurbish- new interiors	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
Elevator A: Replace Mechanical	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166
Elevator B: Replace Mechanical	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166
Elevator: Replace Heat Pump	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140
Elevator Subtotal :	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625
					Pasan	e Category	· Garage						
Garage: General Upkeep					Reger	Category	Carage						
Garage: Upper Deck Re-surface	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500

						u Nevellue	,, Carerre	1		I		I	1
Item Name	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Upper Deck Remediation													
Garage Subtotal :	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500
				Roso	erve Category	ı · Miscellan	eous: Maior	Itoms					
Davis an Asia ball Osal				, ACSC		, miscenari		lems					
Paving: Asphalt Seal Coat	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328
Paving: North near building- Asphalt Repair and Seal	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106
Paving: North side concrete paving													
Paving: South- Asphalt Repair and Seal	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58
Ventilation: Clean North side vents	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667
Ventilation: Clean South Side	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000
Ventilation/North Side: Clean One Floor													
Miscellaneous: Major Items Subtotal :	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159
				Pasarva	Category : I	Miscellaneou	ıs: Ponair an	nd Panaw					
Architectural Exterior: Landscape- Prune Trees	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40
Architectural Exterior: Landscape- Repair Sprinkler Lines													
Architectural Exterior: Replace Glass: Commercial, etc.													

						1	1					2010	
Item Name	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Architectural Interior: Ceilings: Repair and Renew													
Architectural Interior: Flooring: Commercial Spaces													
Architectural Interior: Flooring: Mats	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72
Architectural Interior: Metal Handrails													
Doors: Commercial													
Doors: Exterior- Replace													
Doors: Interior													
MIscellaneous: Paving: Repair Sidewalks													
Miscellaneous: Office Equipment	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167
Miscellaneous: Office- Replace Furniture													
Miscellaneous: Parking- Bicycle Racks													
Roof: Awning Replace													
Roof: Awning- Repair Mounting													
Roof: Seal Patios (Roofs) and North Porches													
Security: Cameras													
Security: Key / Fob / Entry Guard System													

Item Name	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Security: Lighting- Exterior													
Miscellaneous: Repair and Renew Subtotal :	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279
					Reserve	Category : I	Plumbing						
Plumbing Replace Stack Valves Phase 2													
Plumbing Replace Stack Valves- Phase 3													
Plumbing Phase 3: Asbestos abatement													
Plumbing Remediation													
Pipe Repair- Manifold Line													
Plumbing: General Upgrade	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000
Plumbing Subtotal:	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000
					Resei	rve Category	: Roof						
Roof: Consultant													
Roof: Building Roof and Flat Roofs (4)	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571
Roof: Re-Roof 2nd Floor Patio	\$ 1,775	\$ 1,775	\$ 1,775	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420
Roof: East Portico- Rebuild & Re-Roof	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596
North Porches- Remediate													
Roof Subtotal :	\$ 5,942	\$ 5,942	\$ 5,942	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587
					Pasari	e Category :	Socurity						

Item Name	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Security: Garage Roll- up Gates	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667
Security: Fencing	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963
Security Subtotal:	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630
					Reserve	Category : I	Windows						
Windows: Replace Frames and Glass													
Total Revenue :	\$ 93,877	\$ 93,877	\$ 93,877	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050

Item Name	2042	2043	2044	2045	2046	2047	2048	2049
R	eserve Cate	gory : Archi	tectural Exte	rior: Paint a	nd Maintain	1		
Seal exterior seams and joints								
Seal Aggregate Panels								
Maintain brick: point up, clean and seal								
Paint Building Exterior	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323	\$ 8,323
Paint Garage	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021	\$ 1,021
Wash the Building								
Wash the Garage								
Architectural Exterior: Paint and Maintain Subtotal :	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344	\$ 9,344
	R	eserve Cate	gory : Archit	tectural Inter	rior: Flooring	<u> </u>		
Flooring: Hallway Carpets- Replace	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961	\$ 3,961
Flooring: Linoleum- North Hallway	\$ 487	\$ 487	\$ 487	\$ 4 87	\$ 487	\$ 487	\$ 487	\$ 487
Flooring: Lobby and East Entry	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490	\$ 490
Architectural Interior: Flooring Subtotal :	\$ <i>4</i> ,938	\$ 4,938	\$ 4 ,938	\$ 4,938	\$ 4,938	\$ 4,938	\$ 4,938	\$ 4,938
	F	Reserve Cate	gory : Archi	tectural Inte	rior: Lighting	1		
Lighting: North Hallway- Renew	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176	\$ 176
Lighting: Residence Floors- Renew	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077	\$ 1,077
Architectural Interior: Lighting Subtotal:	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253	\$ 1,253
	Reserve (Category : A	rchitectural	Interior: Lob	by & Office I	Remodel		

	20.0	umg omau	jusieu Kev		aromaar re			,
Item Name	2042	2043	2044	2045	2046	2047	2048	2049
Lobby & Office Remodel	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911
Lobby Remodel: Work by Others								
Architectural Interior: Lobby & Office Remodel Subtotal :	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911	\$ 911
	Resi	erve Categoi	ry : Architect	tural Interior	· Paint and S	Seal		
Paint Residential	7,00	or re outegor	Aronneo					
Hallways	\$ 4,265	\$ <i>4</i> ,265	\$ 4,265	\$ <i>4</i> ,265	\$ 4,265	\$ 4,265	\$ 4,265	
Paint 1st Floor Hallway	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	\$ 763	
Paint Stairways	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	\$ 2,000	
Paint Residential Floor Maintenance Doors: Elevators, Stairs, Janitor & Garbage	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750	\$ 2,750
Architectural Interior: Paint and Seal Subtotal :	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 9,778	\$ 2,750
		Reserv	ve Category	: Boiler (Hot	Water)			
Boiler: Replace Key Parts	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547	\$ 2,547
			Reserve Cat	egory : Dooi	rs			
Door: South Main Entry								
Door: East Entry ADA upgrade								
Door: North Entry ADA Upgrade								
Door: North Stairway Entrance								

Item Name	2042	2043	2044	2045	2046	2047	2048	2049
Doors: Stairway- Floors 2 and 3								
Door: South Main Entry- Remedial Work								
Doors Subtotal :								
		Re	eserve Categ	orv : Electri	ical			
Electrical: Replace sub-panel in ECC Room								
Electrical: Replace hallway sub-panels								
Electrical: Maintain and Repair	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
Electrical Subtotal:	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
		R	eserve Cate	gory · Fleva	for			
Elevator Consultants	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259	\$ 259
Elevator: Work by Others	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394	\$ 394
Elevator: Refurbish- new interiors	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500	\$ 1,500
Elevator A: Replace Mechanical	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166
Elevator B: Replace Mechanical	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166	\$ 6,166
Elevator: Replace Heat Pump	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140	\$ 140
Elevator Subtotal :	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625	\$ 14,625
			Reserve Cate	egory : Garae	ae			
Garage: General Upkeep								
Garage: Upper Deck Re-surface	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500

				1	alcilual i			
Item Name	2042	2043	2044	2045	2046	2047	2048	2049
Upper Deck Remediation								
Garage Subtotal:	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500	\$ 5,500
		Danamus Ca		!!	Maiaw Kamaa			
		Reserve Ca	tegory : Mis	cenaneous:	wajor items			
Paving: Asphalt Seal Coat	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328	\$ 328
Paving: North near building- Asphalt Repair and Seal	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106	\$ 106
Paving: North side concrete paving								
Paving: South- Asphalt Repair and Seal	\$ <i>5</i> 8	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58	\$ 58
Ventilation: Clean North side vents	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667
Ventilation: Clean South Side	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000	\$ 1,000
Ventilation/North Side: Clean One Floor								
Miscellaneous: Major Items Subtotal :	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159	\$ 3,159
	D.	sorvo Catao	ory : Miscell	lanaque: Pai	nair and Ban	0147		
Architectural Exterior: Landscape- Prune Trees	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40	\$ 40
Architectural Exterior: Landscape- Repair Sprinkler Lines								
Architectural Exterior: Replace Glass: Commercial, etc.								

Item Name	2042	2043	2044	2045	2046	2047	2048	2049
Architectural Interior: Ceilings: Repair and Renew								
Architectural Interior: Flooring: Commercial Spaces								
Architectural Interior: Flooring: Mats	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72	\$ 72
Architectural Interior: Metal Handrails								
Doors: Commercial								
Doors: Exterior- Replace								
Doors: Interior								
MIscellaneous: Paving: Repair Sidewalks								
Miscellaneous: Office Equipment	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167	\$ 167
Miscellaneous: Office- Replace Furniture								
Miscellaneous: Parking- Bicycle Racks								
Roof: Awning Replace								
Roof: Awning- Repair Mounting								
Roof: Seal Patios (Roofs) and North Porches								
Security: Cameras								
Security: Key / Fob / Entry Guard System								

Item Name	2042	2043	2044	2045	2046	2047	2048	2049
Security: Lighting- Exterior								
Miscellaneous: Repair and Renew Subtotal :	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279	\$ 279
		Re	eserve Categ	ory : Plumb	ing			
Plumbing Replace Stack Valves Phase 2								
Plumbing Replace Stack Valves- Phase 3								
Plumbing Phase 3: Asbestos abatement								
Plumbing Remediation								
Pipe Repair- Manifold Line								
Plumbing: General Upgrade	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	
Plumbing Subtotal :	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	\$ 30,000	
			Reserve Ca	tegory : Roo	f			
Roof: Consultant								
Roof: Building Roof and Flat Roofs (4)	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571	\$ 3,571
Roof: Re-Roof 2nd Floor Patio	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420	\$ 1,420
Roof: East Portico- Rebuild & Re-Roof	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596	\$ 596
North Porches- Remediate								
Roof Subtotal:	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587	\$ 5,587
		R	Reserve Cate	gory : Secur	rity			

Item Name	2042	2043	2044	2045	2046	2047	2048	2049
Security: Garage Roll- up Gates	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667	\$ 1,667
Security: Fencing	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963	\$ 1,963
Security Subtotal:	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630	\$ 3,630
		R	eserve Categ	gory : Windo	ws			
Windows: Replace								
Frames and Glass								
Total Revenue :	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 93,050	\$ 56,022

WT 2018 Funding Study - Expenses by Item and by Calendar Year

Item Description	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035
		'					Reserve C	ategory : Arch	itectural Exte	rior: Paint and	l Maintain					'	'			
Seal exterior seams and joints																				
Seal Aggregate Panels																				
Maintain brick: point up, clean and seal																				
Paint Building Exterior										\$ 124,840										
Paint Garage										\$ 15,316										
Wash the Building																				
Wash the Garage																				
Category Subtotal :										\$ 140,156										
		'					D	0-4	A b id	l lada sia sa Ela a					'	'	<u>'</u>			
Floorings Hallway Comments							Rese	ive Category	Arcnitectural	Interior: Floo	riilg									
Flooring: Hallway Carpets- Replace	\$ 39,614										\$ 39,614									
Flooring: Linoleum- North Hallway	\$ 4,869										\$ 4,869									
Flooring: Lobby and East Entry																\$ 11,750				
Category Subtotal :	\$ 44,483										\$ 44,483					\$ 11,750				
		·						0-4	A b id= =d	I Interior: Ligh	45									
Lighting: North Hallway- Renew							Kese	ve category .	Architectural	interior. Light	\$ 1,760									
Lighting: Residence Floors-											ψ 1,700									
Renew		\$ 10,768										\$ 10,768								
Category Subtotal :		\$ 10,768									\$ 1,760	\$ 10,768								
							Reserve Cate	gory · Archite	ctural Interior	: Lobby & Offic	re Remodel									
Lobby & Office Remodel						•	Teser re oute,	gory . Aronne	Turur micrior	LODDY & OM	oc remoder					\$ 18,227				
Lobby Remodel: Work by Others																ψ 10,221				
Category Subtotal :																\$ 18,227				
Category Subtotal .																ψ 10,227				
							Reserve	Category : A	chitectural In	terior: Paint a	nd Seal									
Paint Residential Hallways									\$ 51,180											
	\$ 3,050				\$ 3,050				\$ 3,050				\$ 3,050				\$ 3,050			
Paint 1st Floor Hallway									\$ 24,000											
Paint 1st Floor Hallway Paint Stairways																				
<u> </u>					\$ 16,500						\$ 16,500						\$ 16,500			

Item Description	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035
									egory : Boile											
Boiler: Replace Key Parts										(\$ 30,562								
Boller. Replace Rey Farts												\$ 50,502								
								Reser	ve Category :	Doors										
Door: South Main Entry	\$ 9,483																			
Door: East Entry ADA upgrade			\$ 4,000																	
Door: North Entry ADA Upgrade			\$ 4,000																	
Door: North Stairway Entrance	\$ 3,429																			
Doors: Stairway- Floors 2 and 3	\$ 5,292																			
Door: South Main Entry- Remedial Work		\$ 517																		
Category Subtotal :	\$ 18,204	\$ 517	\$ 8,000																	
'	<u> </u>								. 0-4											
Flactrical Daulana sub manulin								Reserve	Category : E	ectricai										
Electrical: Replace sub-panel in ECC Room																				
Electrical: Replace hallway sub- panels																				
Electrical: Maintain and Repair								\$ 15,000										\$ 15,000		
Category Subtotal :								\$ 15,000										\$ 15,000		
								Reserv	e Category :	Elevator										
Elevator Consultants																				
Elevator: Work by Others																				
Elevator: Refurbish- new interiors						\$ 9,000						\$ 9,000						\$ 9,000		
Elevator A: Replace Mechanical																				
Elevator B: Replace Mechanical																				
Elevator: Replace Heat Pump															\$ 2,100					
Category Subtotal :						\$ 9,000						\$ 9,000			\$ 2,100			\$ 9,000		
0 ,																				
								Reser	e Category :	Garage					ſ	ſ	ſ			
Garage: General Upkeep																				
Garage: Upper Deck Re-surface				\$ 275,000																
Upper Deck Remediation		\$ 10,550																		
Category Subtotal :		\$ 10,550		\$ 275,000																
							Res	erve Categor	y : Miscelland	eous: Major Ite	ems									
Paving: Asphalt Seal Coat							\$ 1,970						\$ 1,970						\$ 1,970	

Reserve Category : Miscellaneous: Repair and Renew						VV 1 20	718 Fun	aing St	uay Exp	enses k	y Calen	idar Yea	r - Con	inuea							
Assert Method section of the control	Item Description	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035
Marie Mari			\$ 1,270												\$ 1,270						
Second	-																				
Note			\$ 700												\$ 700						
Maritan								\$ 25,000													
Category Substant Cate	/entilation: Clean South Side							\$ 15,000													
Architectural Exertor Arch							\$ 5,000														
Architectural Extensor: Landscape-Purpe Trees Architectural Intensor: Expenser Glass: Commercial, etc. Architectural Intensor: Callings: Repair and Remore Remore Repair and Remore Repair and Remore Remor	Category Subtotal :		\$ 1,970				\$ 5,000	\$ 41,970						\$ 1,970	\$ 1,970					\$ 1,970	
Architectural Exterior: Landinage-Prints Trees								Reserv	e Category : I	Miscellaneous	: Repair and	Renew									
Landscape Repair Sprinkler Lines Class: Commercial, etc. Architectural Interior: Replace Class: Commercial, etc. Architectural Interior: Plooring: Commercial Spaces Architectural Interior: Replace Doors: Commercial Doors: Commercial Doors: Commercial Doors: Commercial Doors: Commercial Doors: Plooring: Miscellaneous: Ploring: Repair Miscellaneous: Cliffice Equipment Miscellaneous: Plarking- Brycle Realis Spaces Sp									V .												
Glass: Commercial, etc. Glass: Commercial etc. Glass: Glas	andscape- Repair Sprinkler									\$ 500											
Repair and Renew Repair and Renew	·									\$ 1,000											
Commercial Spaces Image: Commerc										\$ 3,000											
Mats 5.00 1.00 <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>\$ 4,500</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>										\$ 4,500											
Handrails Image: Commercial of the Control of Co			\$ 504							\$ 504							\$ 504				
Coors: Exterior Replace 1										\$ 1,750											
Doors: Interior Image: Control of the con	Doors: Commercial									\$ 3,000											
Miscellaneous: Parking- Funiture Miscellaneous: Parking- Bicycle Racks Miscellaneous: Office Replace Funiture Miscellaneous: Parking- Bicycle Racks Miscellaneous	Doors: Exterior- Replace									\$ 3,000											
Sidewalks Image: Control of the Equipment of the Eq	Doors: Interior									\$ 5,970											
Miscellaneous: Office- Replace Furniture Company of the Property of th										\$ 3,038											
Furniture Image: Control of the control o	Miscellaneous: Office Equipment									\$ 1,500									\$ 1,500		
Bicycle Racks 6 6 6 1,050 6	· ·									\$ 1,500											
	-									\$ 1,050											
Post Aurilian Pansi Mauritin	Roof: Awning Replace									\$ 9,500											
Toui. Awning-	Roof: Awning- Repair Mounting									\$ 2,500											

Item Description	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035
Roof: Seal Patios (Roofs) and	20.0		20.0	20.0	2020			2020	2027	2020	2020						2002	2000	2007	
North Porches																				
Security: Cameras							\$ 5,000													
Security: Key / Fob / Entry Guard System	\$ 2,351																			
Security: Lighting- Exterior							\$ 8,000													
Category Subtotal :	\$ 2,351	\$ 504					\$ 13,000		\$ 44,312							\$ 504		\$ 1,500		
								Reserve	Category : Pi	lumbina										
Plumbing Replace Stack Valves Phase 2	\$ 17,915									<u> </u>										
Plumbing Replace Stack Valves- Phase 3		\$ 36,542																		
Plumbing Phase 3: Asbestos abatement		\$ 3,946																		
Plumbing Remediation			\$ 82,000																	
Pipe Repair- Manifold Line		\$ 5,100																		
Plumbing: General Upgrade								\$ 150,000					\$ 150,000					\$ 150,000		
Category Subtotal :	\$ 17,915	\$ 45,588	\$ 82,000					\$ 150,000					\$ 150,000					\$ 150,000		
Roof: Consultant								Reser	ve Category :	Roof										
Roof: Building Roof and Flat																				
Roofs (4)											\$ 75,000									
Roof: Re-Roof 2nd Floor Patio																\$ 28,393				
Roof: East Portico-Rebuild & Re-Roof	\$ 5,364									\$ 5,364									\$ 5,364	
North Porches- Remediate						\$ 18,000														
Category Subtotal :	\$ 5,364					\$ 18,000				\$ 5,364	\$ 75,000					\$ 28,393			\$ 5,364	
								Reserve	e Category : S	Security					<u>'</u>		<u> </u>			
Security: Garage Roll-up Gates							\$ 30,000													
Security: Fencing																				
Category Subtotal :							\$ 30,000													
								Reserve	Category : W	/indows					<u>'</u>					
Windows: Replace Frames and																				
Glass																				
Expense Totals :	\$ 91,367	\$ 69,897	\$ 90,000	\$ 275,000	\$ 19,550	\$ 32,000	\$ 84,970	\$ 165,000	\$ 122,541	\$ 145,520	\$ 137,743	\$ 50,330	\$ 155,020	\$ 1,970	\$ 2,100	\$ 58,874	\$ 19,550	\$ 175,500	\$ 7,334	
	, ,,,,,	, -2,007		, = . 0,000	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, -2,000	,		, _ ,	,	,, .		,	,0.0	,.00	, - J, J, T	, ,,,,,,,,,	,,,,,,	, ., ,	

Item Description	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049
				Reserve Cat	egory : Archit	ectural Ext	erior: Paint	and Maintain		'			'	
Seal exterior seams and joints														
Seal Aggregate Panels														
Maintain brick: point up, clean and seal														
Paint Building Exterior					\$ 124,840									
Paint Garage					\$ 15,316									
Wash the Building														
Wash the Garage														
Category Subtotal :					\$ 140,156									
				Reserv	e Category : A	Architectura	al Interior: F	looring						
Flooring: Hallway Carpets- Replace	\$ 39,614										\$ 39,614			
Flooring: Linoleum- North Hallway	\$ 4,869										\$ 4,869			
Flooring: Lobby and East Entry														
Category Subtotal :	\$ 44,483										\$ 44,483			
				Pagaria	e Category : A	l vahitaatuur	l Interior I	inhtina						
Lighting: North Hallway- Renew	\$ 1,760			Neserv	e category . A	dronneoture	interior. L	igitang			\$ 1,760			
Lighting: Residence Floors- Renew		\$ 10,768										\$ 10,768		
Category Subtotal :	\$ 1,760	\$ 10,768									\$ 1,760	\$ 10,768		
			D-		A			O## D	-1				<u>'</u>	
Lobby & Office Remodel			Ke:	serve Calego	ory : Architect	urai interio	LODDY & C	Jince Remod						
Lobby Remodel: Work by Others														
Category Subtotal :														
Category Subtotal :				Reserve C	Category : Arc	hitectural li	nterior: Pair	nt and Seal						
Paint Residential Hallways	\$ 51,180			Reserve C	Category : Arc	hitectural li	nterior: Pair	nt and Seal					\$ 51,180	
	\$ 51,180 \$ 3,050			Reserve C	Category : Arc	hitectural li	nterior: Pair	nt and Seal	\$ 3,050				\$ 51,180 \$ 3,050	
Paint Residential Hallways				Reserve C		hitectural lı	nterior: Pair	t and Seal	\$ 3,050					
Paint Residential Hallways Paint 1st Floor Hallway	\$ 3,050		\$ 16,500	Reserve C		hitectural li	nterior: Pair	t and Seal	\$ 3,050 \$ 16,500				\$ 3,050	

Item Description	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049
					Reserve Categ	gory : Boile	r (Hot Water	•)					•	
Boiler: Replace Key Parts				\$ 30,562										
					Reserve	Category	: Doors							
Door: South Main Entry														
Door: East Entry ADA upgrade														
Door: North Entry ADA Upgrade														
Door: North Stairway Entrance														
Doors: Stairway- Floors 2 and 3														
Door: South Main Entry- Remedial Work														
Category Subtotal :														
					Reserve (Category :	Electrical							
Electrical: Replace sub-panel in ECC Room														
Electrical: Replace hallway sub- panels														
Electrical: Maintain and Repair								\$ 15,000						
Category Subtotal :								\$ 15,000						
					Reserve	Category :	Elevator							
Elevator Consultants														
Elevator: Work by Others														
Elevator: Refurbish- new interiors				\$ 9,000						\$ 9,000				
Elevator A: Replace Mechanical														
Elevator B: Replace Mechanical														
Elevator: Replace Heat Pump										\$ 2,100				
Category Subtotal :				\$ 9,000						\$ 11,100				
					Reserve	Category :	Garage							
Garage: General Upkeep														
Garage: Upper Deck Re-surface														
Upper Deck Remediation														
Category Subtotal :														
				Rese	erve Category	: Miscellan	eous: Major	Items						
Paving: Asphalt Seal Coat					\$ 1,970						\$ 1,970			

Hom Dog - da di - a	2020	2027	2020	2020	2040	2044	20.40	2042	2044	20.45	20.40	2047	2040	2040
Item Description	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049
Paving: North near building- Asphalt Repair and Seal						\$ 1,270								
Paving: North side concrete paving														
Paving: South- Asphalt Repair and Seal						\$ 700								
Ventilation: Clean North side vents		\$ 25,000												
Ventilation: Clean South Side		\$ 15,000												
Ventilation/North Side: Clean One Floor														
Category Subtotal :		\$ 40,000			\$ 1,970	\$ 1,970					\$ 1,970			
				Reserve	Category : Mi	iscellaneou	s: Repair an	d Renew						
Architectural Exterior:							.,							
Landscape- Prune Trees														
Architectural Exterior: Landscape- Repair Sprinkler Lines														
Architectural Exterior: Replace Glass: Commercial, etc.														
Architectural Interior: Ceilings: Repair and Renew														
Architectural Interior: Flooring: Commercial Spaces														
Architectural Interior: Flooring: Mats			\$ 504							\$ 504				
Architectural Interior: Metal Handrails														
Doors: Commercial														
Doors: Exterior- Replace														
Doors: Interior														
MIscellaneous: Paving: Repair Sidewalks														
Miscellaneous: Office Equipment							\$ 1,500							
Miscellaneous: Office- Replace Furniture														
Miscellaneous: Parking- Bicycle Racks														
Roof: Awning Replace														
Roof: Awning- Repair Mounting														

Item Description	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049
Roof: Seal Patios (Roofs) and	2000	2007	2000	2000	2040	2041	2042	2040	2044	2040	2040	2047	2040	2040
North Porches														
Security: Cameras														
Security: Key / Fob / Entry Guard System														
Security: Lighting- Exterior														
Category Subtotal :			\$ 504				\$ 1,500			\$ 504				
Reserve Category : Plumbing														
Plumbing Replace Stack Valves Phase 2														
Plumbing Replace Stack Valves- Phase 3														
Plumbing Phase 3: Asbestos abatement														
Plumbing Remediation														
Pipe Repair- Manifold Line														
Plumbing: General Upgrade			\$ 150,000					\$ 150,000					\$ 150,000	
Category Subtotal :			\$ 150,000					\$ 150,000					\$ 150,000	
					Reserve	e Category	· Roof							
Roof: Consultant					7,000,7	outogo.,								
Roof: Building Roof and Flat Roofs (4)												\$ 75,000		
Roof: Re-Roof 2nd Floor Patio														
Roof: East Portico-Rebuild & Re-Roof								\$ 5,364						
North Porches- Remediate														
Category Subtotal :								\$ 5,364				\$ 75,000		
						0-4	Ci4							
Security: Garage Roll-up Gates					\$ 30,000	Category :	security							
Security: Garage Roll-up Gates Security: Fencing					\$ 3U,UUU									
Category Subtotal :					\$ 30,000									
Category Subiotal :					φ 30,000									
					Reserve C	Category : V	Vindows							
Windows: Replace Frames and Glass														
Expense Totals :	\$ 124,473	\$ 50,768	\$ 167,004	\$ 39,562	\$ 175,176	\$ 1,970	\$ 1,500	\$ 170,364	\$ 19,550	\$ 11,604	\$ 48,213	\$ 85,768	\$ 228,230	

Willamette Towers HOA

Reserves Study 2018

Expense Summary by Year 2016 - 2023

2017 Expense Summary- actual costs

Year	Category	item Name	Expense	Amount		
2017	Architectural Interior: Lighting	Replace lighting floors 2-5 & 7-13 (1st & 6th floor are done).	9,760	9,760		
	Doors	Electrical work at main entry door	517	517		
	Garage: Parking Area Repairs	Remedial work to protect upper deck concrete as-is and to buy time until 2019 complete re-working of the upper deck surface concrete	10,550	10,550		
	Miscellaneous: Major Items: Paving: Asphalt Repair	, , , , , , , , , , , , , , , , , , , ,				
	Miscellaneous: Repair and Renew-	Flooring:	504	504		
	Miscellaneous: Repair and Renew - Security: Equipment for Gates	Gate Maintenance	609	609		
	Plumbing	Riser valve replacement Riser Valve Remediation (Asbestos) Pipe Repair- Replace Manifold line on 1st floor- one time event	36,542 3,946 5,100	45,588		
		2017 Annual Expense Total	69,498	69,498		

6th floor lighting done in 2016: \$1,007.

Combined with this 2017 total, item appears in the Reserves item expenses as \$10,768 for all residential floors (108 fixtures)

Remedial work on the garage upper deck

2018 Expense Summary update

	Catagory	item Name	Expense	Amount
2018	Category Doors	ADA (Americans with Disabilities Act) upgrade for lobby doors; East & North Doors.	8,000	8,000
	Plumbing: Remediation	Planned remediation involves replacing some plumbing parts and treating all lines with compressed air;	82,000	82,000
		2018 Annual Expense Total	90,000	90,000

Placeholder amount: While this work was done in 2017, the billing is due in 2018 Goal is to clear lines as well as possible of interior metal build-up and buy time regarding plumbing pipe replacement.

Investigation leads the MMRRC (Major Maintenance, Repair and Replacement Committee) to believe that this will help clear plumbing lines and put off major plumbing work for up to 10 years.

2019 Expense Summary

	Category	item Name	Expense	Amount
2019	Garage	Replace Upper Deck Surface	275,000	275000
	Miccellaneous, Major Itams	North Side Paving: Alternatives are concrete	0 dollars	
	Miscellaneous: Major Items	(estimated \$50,000), complete asphalt re-paving	provided in	
		2019 Annual Expense Total	275000	275000

Bid may be as low as \$250,000. Tom Weaverling highlights that concrete equipment will be available at the time of the

2020 Expense Summary

	Category	item Name	Expense	Amount
2020	Architectural Interior: Paint and Seal	Paint residential floor doors: elevator, stairs, janitor, garbage, porch access, and fire extinguisher cabinets	16,500	16,500
		Paint 1st Floor Hallways & Doors	3050	3050
		2020 Annual Expense Total	19,550	19,550

Work on choosing colors began in 2017, and there is the expectation that this project should be done when funds materialize.

2021 Expense Summary

Category	item Name	Expense	Amount	
Elevator	Refurbish Interiors	9000	9000	This is a regularly scheduled items, to be done if needed at the time.
Miscellaneous: Major Items - Ventilation	Single-floor trial: Explanation: Tom's plan for the vents has two components- clean the vents (utilizes a powerful suction hose) and add a small fan at the exiting area of the vent to provide a positive flow of air.	5000	5000	Addressing the cost of the garage has meant that all vents being cleaned has been postponed to 2022. This would be a trial run for a method to have positive air flow from each unit. It may require a vote to fund as the cost is above \$2500, the capital improvements non-voted limit set in the documents.
Miscellaneous: Repair and Renew- Roof	Roof: Re-surface North porches	18,000	18,000	Tom estimates a cost at \$1500 per porch. This will cause proper water drainage, which should extend the life of the porch doors and stairway doors.
	2021 Annual Expense Total	32000	32000	

2022 Expense Summary

	Category	item Name	Expense	Amount	
2022		Paving: Asphalt Seal Coat	1970		Regularly scheduled maintenance
	Miscellaneous: Major Items	Ventilation: Clean North Side Vents	25000	41970	We have two major veintilation layouts: one
		Ventilation: Clean South Side Vents	15000		vents out at the north porches and one vents
	Miscellaneous: Repair & Renew	Security Cameras	5000	13000	Regularly scheduled item
	Wilscellaneous. Repail & Renew	Security: Lighting- exterior	8000	13000	Regularly scheduled item
	Security	Garage: Replace or Repair the Roll-up Gates	30000	30000	Regularly scheduled item: depending on need to do so
		2022 Annual Expense Total	84970	84970	

2023 Expense Summary

	Category	item Name	Expense	Amount	
2023	Electrical: Maintain & Repair		15000	15000	Rather generic. We do not want generic items sprinkled through the reserves, but Tom recommends retaining this one.
	Plumbing: Plumbing Remediation	General repairs	150000	150000	The 2018 remediation- to clear the pipes- is reported to "buy us 5 years" regarding repairs to plumbing. There is no reserves item for plumbing replacement. Repairs to failed areas in 2017 cost around \$18,000. The \$150,000 amount is allowing \$30,000 in repairs per year, accumulated in the five years following the pipe-clearing effort. It repeats on a 7 year basis.
		2023 Annual Expense Total		165000]

2024 Major items include Paint Residential Hallways (\$51,800), Paint Stairways (\$24,000), and Miscellaneous Minor items.

The major item is Paint Building and Paint Garage for a combined total of \$140,000.

2026 Major items are the regularly scheduled Flooring: Hallway Carpets (\$40,000) and a new roof, layered on top of our original,

30-year The reserves show our "% funded" growing beyond 100% towards the end of the 30-year scope of the study, but this amount does not take into account that two major items, the elevator replacement and the grounds fencing, will come into